

| | |
|------------|----------------|
| Well: | Alp Fee 24-12A |
| Pad: | J24NW |
| API No: | 0504521808 |
| Permit No: | |

Bradenhead Pressure Report Following Primary Cement Job

| | |
|----------------|------------|
| Date Cemented: | 07/31/2013 |
| Plug Bumped: | Yes |

| | | |
|---|--------|---------|
| Annular Fluid Level After Job (Static or Falling?): | Static | |
| If falling, barrels of mud added until stabilized: | N/A | barrels |

| | |
|---------------|----------|
| WOC Time: | 6 hours |
| Bond Log Run: | Temp log |

| | |
|-------------------|-----|
| Casing Slips Set: | Yes |
|-------------------|-----|

Bradenhead Pressures

| | | |
|---------|---|------|
| 6 hrs: | 0 | psig |
| 12 hrs: | 0 | psig |
| 24 hrs: | 0 | psig |
| 48 hrs: | 0 | psig |
| 72 hrs: | 0 | psig |

Comments

The well was cemented with full returns and the annulus held for 4 hours prior to setting casing slips. A CBL was ran when the rig moved off the pad.