

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
11/19/2013

Document Number:
668601706

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------|--------------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | <input type="checkbox"/> |
| | 297880 | 309645 | QUINT, CRAIG | 2A Doc Num: | |

Operator Information:

OGCC Operator Number: _____

Name of Operator: WIEPKING-FULLERTON ENERGY LLC

Address: 4600 S DOWNING ST

City: ENGLEWOOD State: CO Zip: 80113

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|--------------------------|-----------------|
| HALDE, KERRY | (719) 346-0653 | haldesand@centurytel.net | ALL INSPECTIONS |

Compliance Summary:

QtrQtr: NENW Sec: 30 Twp: 10S Range: 55W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 07/20/2012 | 664000707 | PR | PR | Satisfactory | I | | No |
| 06/29/2012 | 664000672 | PR | PR | Violation | I | | Yes |
| 04/11/2011 | 200308318 | PR | PR | Satisfactory | | | No |
| 01/05/2011 | 200291027 | PR | PR | Satisfactory | | | No |
| 11/02/2010 | 200285003 | CO | PR | Unsatisfactory | | | Yes |
| 10/05/2010 | 200276196 | CO | PR | Unsatisfactory | | | Yes |
| 09/09/2010 | 200270694 | PR | PR | Satisfactory | | | No |
| 01/21/2010 | 200228361 | PR | PR | Unsatisfactory | | | Yes |
| 07/17/2009 | 200215072 | PR | PR | Unsatisfactory | | | Yes |
| 01/06/2009 | 200202177 | PR | WO | Unsatisfactory | | | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|--------------------------------|-------------|-------------------------------------|
| 297880 | WELL | PR | 10/23/2013 | OW | 073-06347 | FORRISTAL RANCH STATE 21-30 #5 | PR | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|----------------------------|-------------------|------|
| Access | Satisfactory | DIRT ROAD THROUGH PASTURE. | | |

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|--------------------|-------------------|---------|
| WELLHEAD | Satisfactory | LEASE SIGN BY UNIT | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|--|------|--------|-------------------|---------|
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Equipment:

| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|---------------------|---|-----------------------------|---|-------------------|---------|
| Ancillary equipment | 5 | Satisfactory | DAY TANK, GAS SCRUBBER, CATHOTIC GENERATOR & RECTIFIER, CHEMICAL TANK W/O CONTAINMENT | | |
| Pump Jack | 1 | Satisfactory | 456 LUFKIN | | |
| Prime Mover | 1 | Satisfactory | E-42 AJAX GAS ENGINE | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------|---|----------|---------------------|-----------------------|
| | | | CENTRALIZED BATTERY | 39.151740,-103.597040 |

S/U/V: Satisfactory Comment: **CENTRAL BATTERY F/(MA-STATE 2, 3, 4, POCKET MONEY 1, FORRISTAL RANCH STATE 21-30 #5) 1300' S**

Corrective Action: _____ Corrective Date: _____

Paint

Condition: _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

Corrective Action _____ Corrective Date _____

Comment _____

Venting:

Yes/No _____ Comment _____

NO _____

Flaring:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 297880

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/UV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/UV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/UV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 297880 Type: WELL API Number: 073-06347 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING, CENTRAL BATTERY F/(MA-STATE 2, 3, 4, POCKET MONEY 1, FORRISTAL RANCH STATE 21-30 #5) 1300' S @ 39.15174, -103.59704

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: _____

1003a. Debris removed? _____ CM _____ CA _____ CA Date _____
Waste Material Onsite? _____ CM _____ CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____ CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____ CA _____ CA Date _____
Guy line anchors removed? _____ CM _____ CA _____ CA Date _____
Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

Inspector Name: QUINT, CRAIG

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | MHSP | Fail | |

S/U/V: **Unsatisfactory** Corrective Date: **02/18/2014**

Comment: **CHEMICAL TANK WITH INADEQUATE BERMS**

CA: **REPAIR BERMS OR INSTALL CONTAINMENT (BMP).**

Pits: NO SURFACE INDICATION OF PIT