

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

11/22/2013

Document Number:

673700031

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	<u>297880</u>	<u>309645</u>	<u>Sherman, Susan</u>	<input type="checkbox"/> 2A Doc Num: _____

**Operator Information:**

OGCC Operator Number:

Name of Operator: WIEPKING-FULLERTON ENERGY LLCAddress: 4600 S DOWNING STCity: ENGLEWOOD State: CO Zip: 80113

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
STUM, DUSTIN	(719) 740-0462	dstum562gmail.com	pumper
Halde, Kerry	(719) 340-0329	haldesand@centurytel.net	field operations

**Compliance Summary:**QtrQtr: NENW Sec: 30 Twp: 10S Range: 55W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/20/2012	664000707	PR	PR	Satisfactory	I		No
06/29/2012	664000672	PR	PR	Violation	I		Yes
04/11/2011	200308318	PR	PR	Satisfactory			No
01/05/2011	200291027	PR	PR	Satisfactory			No
11/02/2010	200285003	CO	PR	Unsatisfactory			Yes
10/05/2010	200276196	CO	PR	Unsatisfactory			Yes
09/09/2010	200270694	PR	PR	Satisfactory			No
01/21/2010	200228361	PR	PR	Unsatisfactory			Yes
07/17/2009	200215072	PR	PR	Unsatisfactory			Yes
01/06/2009	200202177	PR	WO	Unsatisfactory			No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297880	WELL	PR	10/23/2013	OW	073-06347	FORRISTAL RANCH STATE 21-30 #5	PR <input checked="" type="checkbox"/>

**Equipment:****Location Inventory**

Inspector Name: Sherman, Susan

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

<b>Signs/Marker:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
CONTAINERS	Satisfactory	TWO CHEMICAL DRUMS. CHECK BERM CAPACITY.		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
Crude Oil	WELLHEAD	<= 5 bbls	PUMPER ON LOCATION TO CLEAN UP SPILL AT TIME OF INSPECTION. SEE ATTACHED PHOTO.	11/22/2013

☐ Multiple Spills and Releases?

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Deadman # & Marked	4	Satisfactory			
Pump Jack	1	Satisfactory			
Prime Mover	1	Satisfactory	NATURAL GAS		

<b>Venting:</b>		
Yes/No	Comment	
NO		

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 297880

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 297880 Type: WELL API Number: 073-06347 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Inspector Name: Sherman, Susan

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Waste Material Onsite? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

Inspector Name: Sherman, Susan

Comment: **PER KERRY HALDE THE RANCHER WANTS CATTLE TO EAT WEEDS**

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	MHSP	Pass	

S/U/V: Satisfactory \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: **RILL CARRYING SEDIMENT OFFSITE ON EAST SIDE OF WELLHEAD PRODUCTION LOCATION. WILL BE FIXED PER CONVERSATION WITH KERRY HALDE.**

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673700126	FORRESTAL RANCH 21_30_5 CHEM	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236689</a>
673700128	FORRESTAL RANCH 21_30_5 IR	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236690">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236690</a>
673700129	FORRESTAL RANCH 21_30_5 IR2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236691">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236691</a>
673700130	FORRESTAL RANCH 21_30_5 RILL	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236692">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236692</a>
673700131	FORRESTAL RANCH 21_30_5 SIGN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236693">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236693</a>
673700132	FORRESTAL RANCH 21_30_5 SPILL	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236694">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236694</a>