

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/20/2013

Document Number:

663902533

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335648	335648	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:

Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
YOKLEY, BILL		bill.yokley@state.co.us	
Insp., General	970-285-2665	cogcc.inspections@encana.com	

Compliance Summary:

QtrQtr:	NESW	Sec:	22	Twp:	5S	Range:	96W
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/22/2012	663800351			Satisfactory			No

Inspector Comment:No evidence of N. PARACHUTE WF511B-22 K22 5 being drilled**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283955	WELL	PR	05/15/2008	GW	045-12041	N. PARACHUTE WF11B K22 596	PR
283956	WELL	PR	03/30/2008	GW	045-12040	N. PARACHUTE WF06B K22 596	PR
283957	WELL	PR	03/07/2007	GW	045-12039	N. PARACHUTE WF05D K22 596	PR
283958	WELL	PR	02/01/2011	GW	045-12038	N. PARACHUTE WF16B K22 596	PR
283959	WELL	PR	03/07/2007	GW	045-12037	N. PARACHUTE WF05B K22 596	PR
283960	WELL	PR	01/17/2008	GW	045-12026	N. PARACHUTE WF16B-21 K22 59	PR
283961	WELL	PR	03/23/2006	GW	045-12027	N. PARACHUTE WF 12D K22 596	PR
283962	WELL	PR	03/07/2007	GW	045-12028	N. PARACHUTE WF09D K22 596	PR
283963	WELL	PR	03/23/2006	GW	045-12029	N. PARACHUTE WF 13B K22 596	PR

283964	WELL	DA	05/23/2007	GW	045-12030	N.PARACHUTE WF10D K22 596	DA	<input type="checkbox"/>
283965	WELL	PR	03/07/2007	GW	045-12031	N. PARACHUTE WF14B K22 596	PR	<input type="checkbox"/>
283966	WELL	PR	03/23/2006	GW	045-12032	N.PARACHUTE WF09B K22 596	PR	<input type="checkbox"/>
283967	WELL	PR	03/07/2007	GW	045-12033	N. PARACHUTE WF15D K22 596	PR	<input type="checkbox"/>
283968	WELL	PR	03/07/2007	GW	045-12034	N. PARACHUTE WF15B K22 596	PR	<input type="checkbox"/>
283988	WELL	PR	11/22/2007	GW	045-12035	N. PARACHUTE WF12B K22 596	PR	<input type="checkbox"/>
283991	WELL	PR	08/16/2010	GW	045-12036	N. PARACHUTE WF11D K22 596	PR	<input type="checkbox"/>
292211	WELL	AL	07/07/2011	LO	045-14636	N. PARACHUTE WF511B-22 K22 5	AL	<input checked="" type="checkbox"/>
414496	WELL	PR	02/16/2011	GW	045-18858	N. Parachute WF04A-27 K22 59	PR	<input type="checkbox"/>
414498	WELL	PR	07/08/2011	GW	045-18859	N. Parachute WF03D-27 K22 59	PR	<input type="checkbox"/>
414499	WELL	PR	09/14/2011	GW	045-18860	N. Parachute WF03C-27 K22 59	PR	<input type="checkbox"/>
414510	WELL	PR	09/14/2011	GW	045-18861	N. Parachute WF04B-22 K22 59	PR	<input type="checkbox"/>
414734	WELL	PR	10/10/2011	GW	045-18870	N. Parachute WF15A-22 K22 59	PR	<input type="checkbox"/>
414736	WELL	PR	09/14/2011	GW	045-18871	N. Parachute WF05D-22 K22 59	PR	<input type="checkbox"/>
414739	WELL	PR	07/07/2011	GW	045-18872	N. Parachute WF10A-21 K22 59	PR	<input type="checkbox"/>
414749	WELL	PR	07/13/2011	GW	045-18877	N. Parachute WF04B-27 K22 59	PR	<input type="checkbox"/>
414751	WELL	PR	10/10/2011	GW	045-18878	N. Parachute WF06C-22 K22 59	PR	<input type="checkbox"/>
414752	WELL	PR	09/14/2011	GW	045-18879	N. Parachute WF14D-22 K22 59	PR	<input type="checkbox"/>
414754	WELL	PR	10/10/2011	GW	045-18880	N. Parachute WF11A-22 K22 59	PR	<input type="checkbox"/>
414756	WELL	PR	06/17/2011	GW	045-18881	N. Parachute WF11D-22 K22 59	PR	<input type="checkbox"/>
414758	WELL	PR	04/13/2011	GW	045-18883	N. Parachute WF10D-21 K22 59	PR	<input type="checkbox"/>
414760	WELL	PR	07/07/2011	GW	045-18884	N. Parachute WF14C-22 K22 59	PR	<input type="checkbox"/>
414763	WELL	PR	09/09/2010	GW	045-18887	N. Parachute WF15A-21 K22 59	PR	<input type="checkbox"/>
414764	WELL	PR	05/12/2011	GW	045-18888	N. Parachute WF13D-22 K22 59	PR	<input type="checkbox"/>
414767	WELL	PR	06/17/2011	GW	045-18890	N. PARACHUTE WF03A-27 K22 59	PR	<input type="checkbox"/>
414768	WELL	PR	07/07/2011	GW	045-18891	N. Parachute WF12B-22 K22 59	PR	<input type="checkbox"/>
414769	WELL	PR	04/13/2011	GW	045-18892	N. Parachute WF13C-22 K22 59	PR	<input type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

414772	WELL	PR	06/17/2011	GW	045-18895	N. Parachute WF04D-22 K22 59	PR	
414774	WELL	PR	07/13/2011	GW	045-18896	N. Parachute WF09B-21 K22 59	PR	
414777	WELL	PR	04/13/2011	GW	045-18897	N. PARACHUTE WF08D-21 K22 59	PR	
414779	WELL	PR	09/14/2011	GW	045-18898	N. Parachute WF06B-22 K22 59	PR	
414780	WELL	PR	07/13/2011	GW	045-18899	N. Parachute WF04C-27 K22 59	PR	
414783	WELL	PR	06/17/2011	GW	045-18901	N. Parachute WF04C-22 K22 59	PR	
414786	WELL	PR	09/07/2010	GW	045-18903	N. Parachute WF13B-22 K22 59	PR	
414788	WELL	PR	09/08/2010	GW	045-18904	N. Parachute WF12C-22 K22 59	PR	
414793	WELL	PR	04/13/2011	GW	045-18908	N. Parachute WF09D-21 K22 59	PR	
414797	WELL	PR	09/14/2011	GW	045-18911	N. Parachute WF05C-22 K22 59	PR	
414802	WELL	PR	09/14/2011	GW	045-18914	N. Parachute WF03B-27 K22 59	PR	
414806	WELL	PR	05/12/2011	GW	045-18916	N. Parachute WF10B-21 K22 59	PR	
414807	WELL	PR	09/14/2011	GW	045-18917	N. Parachute WF14B-22 K22 59	PR	
414816	WELL	PR	07/23/2010	GW	045-18919	N. Parachute WF16A-21 K22 59	PR	
414819	WELL	PR	09/09/2010	GW	045-18920	N. Parachute WF16C-21 K22 59	PR	
414821	WELL	PR	07/29/2010	GW	045-18921	N. Parachute WF16D-21 K22 59	PR	
414822	WELL	PR	10/10/2011	GW	045-18922	N. Parachute WF15C-22 K22 59	PR	
425754	PIT		10/05/2011		-	WF K22 596		

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>2</u>	Wells: <u>52</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>4</u>	Separators: <u>26</u>	Electric Motors: <u>4</u>
Gas or Diesel Mortors: <u>3</u>	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: <u>3</u>	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>2</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: <u>1</u>	Flare: _____	Fuel Tanks: <u>1</u>

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Inspector Name: LONGWORTH, MIKE

☐ Multiple Spills and Releases?

Venting:

Yes/No

Comment

Flaring:

Type

Satisfactory/Unsatisfactory

Comment

Corrective Action

CA Date

Predrill

Location ID: 335648

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Agency	kubeczkod	Land Assessment COAs Approved by Operator: COA 2 - Location may be in a sensitive area due to shallow groundwater; therefore if drilling pits intercept groundwater the pit must be lined or a closed loop system must be used.	11/12/2009
Agency	kubeczkod	Land Assessment COAs Approved by Operator: COA 4 - Location is in a sensitive area because of close proximity to surface water, therefore, operator must ensure 150 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations.	11/12/2009
Agency	kubeczkod	Land Assessment COAs Approved by Operator: COA 5 - Operator must implement best management practices to contain any unintentional release of fluids.	11/12/2009
Agency	kubeczkod	Land Assessment COAs Approved by Operator: COA 1 - Location is in a sensitive area because of shallow groundwater; therefore, either a lined drilling pit or closed loop system must be implemented.	11/12/2009

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____	Date: _____
Stormwater:	
Comment: _____	
Staking:	
On Site Inspection (305):	
<u>Surface Owner Contact Information:</u>	
Name: _____	Address: _____
Phone Number: _____	Cell Phone: _____
<u>Operator Rep. Contact Information:</u>	
Landman Name: _____	Phone Number: _____
Date Onsite Request Received: _____	Date of Rule 306 Consultation: _____
Request LGD Attendance: _____	
<u>LGD Contact Information:</u>	
Name: _____	Phone Number: _____ Agreed to Attend: _____
<u>Summary of Landowner Issues:</u>	
<u>Summary of Operator Response to Landowner Issues:</u>	
<u>Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:</u>	

Facility

Facility ID: 292211	Type: WELL	API Number: 045-14636	Status: AL	Insp. Status: AL
---------------------	------------	-----------------------	------------	------------------

Environmental

Spills/Releases:		
Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____ Long _____	
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:		
DWR Receipt Num: _____	Owner Name: _____	GPS : _____ Lat _____ Long _____

Field Parameters:	
Sample Location: _____	
Emission Control Burner (ECB): _____	
Comment: _____	
Pilot: _____	Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Inspector Name: LONGWORTH, MIKE

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: OTHER

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: OTHER

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Inspector Name: LONGWORTH, MIKE

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
------------------	-----------------	-------------------------	-----------------------	---------------	--------------------------	---------

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT