

Location SG-22-57 Date 9/16/13Project / Client WPX8999 14' 20" M. Garde - K. Blau

cmt pt now covered -

- material removed away from here.

- Heavy rains - but no E.C.P. run off  
off location. PASS Erosion!

- native stream to N.W.

work marked to S