
WPX ENERGY ROCKY MOUNTAIN LLC-EBUS

**RWF 324-25
RULISON
Garfield County , Colorado**

**Cement Surface Casing
01-Jan-2014**

Post Job Report

The Road to Excellence Starts with Safety

| | | | |
|---|---------------------------|---|---------------------------------|
| Sold To #: 300721 | Ship To #: 3123569 | Quote #: | Sales Order #: 901010585 |
| Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS | | Customer Rep: | |
| Well Name: RWF | | Well #: 324-25 | API/UWI #: |
| Field: RULISON | City (SAP): RIFLE | County/Parish: Garfield | State: Colorado |
| Contractor: NABORS | | Rig/Platform Name/Num: 577 | |
| Job Purpose: Cement Surface Casing | | | |
| Well Type: Development Well | | Job Type: Cement Surface Casing | |
| Sales Person: MAYO, MARK | | Srvc Supervisor: CASTILLO, FRANCISCO | MBU ID Emp #: 513620 |

Job Personnel

| HES Emp Name | Exp Hrs | Emp # | HES Emp Name | Exp Hrs | Emp # | HES Emp Name | Exp Hrs | Emp # |
|--------------------------|---------|--------|----------------|---------|--------|-----------------|---------|--------|
| CASTILLO, FRANCISCO P | 6 | 513620 | HYDE, DUSTIN C | 6 | 453940 | SINCLAIR, DAN J | 6 | 338784 |
| WILSON, BENJAMIN Wallace | 6 | 533647 | | | | | | |

Equipment

| HES Unit # | Distance-1 way |
|------------|----------------|------------|----------------|------------|----------------|------------|----------------|
| 10297346 | 60 mile | 10998054 | 60 mile | 11259884 | 60 mile | | |

Job Hours

| Date | On Location Hours | Operating Hours | Date | On Location Hours | Operating Hours | Date | On Location Hours | Operating Hours |
|--------|-------------------|-----------------|------|-------------------|-----------------|------|-------------------|-----------------|
| 1/1/14 | 6 | 1 | | | | | | |

TOTAL Total is the sum of each column separately

Job

Job Times

| Formation Name | Top | Bottom | 1145 | Called Out | Date | Time | Time Zone |
|------------------------|----------|-------------------|----------|---------------|-----------------|-------|-----------|
| Formation Depth (MD) | | SURFACE | Bottom | 1145 | 01 - Jan - 2014 | 00:30 | MST |
| Form Type | | BHST | | On Location | 01 - Jan - 2014 | 05:00 | MST |
| Job depth MD | 1155. ft | Job Depth TVD | 1155. ft | Job Started | 01 - Jan - 2014 | 08:09 | MST |
| Water Depth | | Wk Ht Above Floor | 3. ft | Job Completed | 01 - Jan - 2014 | 09:06 | MST |
| Perforation Depth (MD) | From | To | | Departed Loc | 01 - Jan - 2014 | 11:00 | MST |

Well Data

| Description | New / Used | Max pressure psig | Size in | ID in | Weight lbm/ft | Thread | Grade | Top MD ft | Bottom MD ft | Top TVD ft | Bottom TVD ft |
|-------------|------------|-------------------|---------|-------|---------------|--------|-------|-----------|--------------|------------|---------------|
| | | | | | | | | | | | |

Tools and Accessories

| Type | Size | Qty | Make | Depth | Type | Size | Qty | Make | Depth | Type | Size | Qty | Make |
|--------------|-------|-----|------|-------|-------------|------|-----|------|-------|----------------|-------|-----|------|
| Guide Shoe | 9.625 | 1 | WTF | 1145 | Packer | | | | | Top Plug | 9.625 | 1 | HES |
| Float Shoe | | | | | Bridge Plug | | | | | Bottom Plug | | | |
| Float Collar | 9.626 | 1 | WTF | 1100 | Retainer | | | | | SSR plug set | | | |
| Insert Float | | | | | | | | | | Plug Container | 9.625 | 1 | HES |
| Stage Tool | | | | | | | | | | Centralizers | 9.625 | 8 | WTF |

Miscellaneous Materials

| Gelling Agt | Conc | Surfactant | Conc | Acid Type | Qty | Conc | % |
|---------------|------|------------|------|-----------|------|------|---|
| Treatment Fld | Conc | Inhibitor | Conc | Sand Type | Size | Qty | |

Fluid Data

Stage/Plug #: 1

| Fluid # | Stage Type | Fluid Name | Qty | Qty uom | Mixing Density lbm/gal | Yield ft ³ /sk | Mix Fluid Gal/sk | Rate bbl/min | Total Mix Fluid Gal/sk |
|---------|------------|------------|-----|---------|------------------------|---------------------------|------------------|--------------|------------------------|
| | | | | | | | | | |

Stage/Plug #: 1

| Fluid # | Stage Type | Fluid Name | Qty | Qty uom | Mixing Density uom | Yield uom | Mix Fluid uom | Rate uom | Total Mix Fluid uom |
|---------|------------|------------|-----|---------|--------------------|-----------|---------------|----------|---------------------|
| | | | | | | | | | |

| Stage/Plug #: 1 | | | | | | | | | | |
|--|--------------------------|------------------------------|-----------|-----------------------------------|------------------------|---------------------------|------------------|--------------|------------------------|--|
| Fluid # | Stage Type | Fluid Name | Qty | Qty uom | Mixing Density lbm/gal | Yield ft ³ /sk | Mix Fluid Gal/sk | Rate bbl/min | Total Mix Fluid Gal/sk | |
| 1 | Fresh Water Spacer | | 20.00 | bbl | . | .0 | .0 | 4 | | |
| 2 | VariCem GJ! Lead Cement | VARICEM (TM) CEMENT (452009) | 146.0 | sacks | 12.3 | 2.38 | 13.75 | 7 | 13.75 | |
| 13.75 Gal | | FRESH WATER | | | | | | | | |
| 3 | VariCem GJ1 Tail Cement | VARICEM (TM) CEMENT (452009) | 160.0 | sacks | 12.8 | 2.11 | 11.75 | 7 | 11.75 | |
| 11.75 Gal | | FRESH WATER | | | | | | | | |
| 4 | Fresh Water Displacement | | 86.00 | bbl | . | .0 | .0 | 10 | | |
| Calculated Values | | | Pressures | | | Volumes | | | | |
| Displacement | 86 | Shut In: Instant | | Lost Returns | NONE | Cement Slurry | 122 | Pad | | |
| Top Of Cement | SURFACE | 5 Min | | Cement Returns | 20 | Actual Displacement | | Treatment | | |
| Frac Gradient | | 15 Min | | Spacers | 20 | Load and Breakdown | | Total Job | 229 | |
| Rates | | | | | | | | | | |
| Circulating | RIG | Mixing | 7 | Displacement | 10 | Avg. Job | | | | |
| Cement Left In Pipe | Amount | 45 ft | Reason | Shoe Joint | | | | | | |
| Frac Ring # 1 @ | ID | Frac ring # 2 @ | ID | Frac Ring # 3 @ | ID | Frac Ring # 4 @ | ID | | | |
| The Information Stated Herein Is Correct | | | | Customer Representative Signature | | | | | | |


The Road to Excellence Starts with Safety

| | | | |
|---|---------------------------|---|---------------------------------|
| Sold To #: 300721 | Ship To #: 3123569 | Quote #: | Sales Order #: 901010585 |
| Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS | | Customer Rep: | |
| Well Name: RWF | | Well #: 324-25 | API/UWI #: |
| Field: RULISON | City (SAP): RIFLE | County/Parish: Garfield | State: Colorado |
| Legal Description: | | | |
| Lat: | | Long: | |
| Contractor: NABORS | | Rig/Platform Name/Num: 577 | |
| Job Purpose: Cement Surface Casing | | | Ticket Amount: |
| Well Type: Development Well | | Job Type: Cement Surface Casing | |
| Sales Person: MAYO, MARK | | Srvc Supervisor: CASTILLO, FRANCISCO | MBU ID Emp #: 513620 |

| Activity Description | Date/Time | Cht # | Rate bbl/min | Volume bbl | | Pressure psig | | Comments |
|---------------------------------------|---------------------|-------|--------------|------------|-------|---------------|--------|--|
| | | | | Stage | Total | Tubing | Casing | |
| Call Out | 01/01/2014 00:30 | | | | | | | ON LOCATION AT 05:30 HRS |
| Pre-Convoy Safety Meeting | 01/01/2014 02:50 | | | | | | | ALL HES PERSONEL |
| Crew Leave Yard | 01/01/2014 03:00 | | | | | | | |
| Arrive At Loc | 01/01/2014 05:00 | | | | | | | RIG WAS STILL RUNNING CASING/LANDED CASING 07:00 AM/CIRCULATED WELL FOR 1 HR |
| Assessment Of Location Safety Meeting | 01/01/2014 05:30 | | | | | | | ALL HES PERSONEL |
| Rig-Up Equipment | 01/01/2014 06:00 | | | | | | | 1-ELITE, 1-660 BULK TRUCKS, 2" PUMPING IRON, 9.625" PLUG CONTAINER AND QUICKLATCH |
| Rig-Up Completed | 01/01/2014 07:00 | | | | | | | |
| Pre-Job Safety Meeting | 01/01/2014 07:55 | | | | | | | ALL HES PERSONEL AND RIG CREW |
| Start Job | 01/01/2014 08:09 | | | | | | | TD-1155', OH-13.5", TP-1145', SJ-45', FC-1100', CSG-9.625", 32.3#, H-40, MUD 10.3 PPG, VISC-70 |
| Pump Water | 01/01/2014 08:10 | | 2 | 2 | | | 40.0 | FILL LINES |
| Pressure Test | 01/01/2014 08:13 | | 0.2 | 0.2 | | | | STALL OUT TEST WITH 2214 PSI |
| Pressure Test | 01/01/2014 08:15 | | 0.2 | 0.2 | | | | PRESSURE TEST LINES WITH 4000 PSI |

| Activity Description | Date/Time | Cht # | Rate bbl/min | Volume bbl | | Pressure psig | | Comments |
|--|---------------------|-------|--------------|------------|-------|---------------|--------|---|
| | | | | Stage | Total | Tubing | Casing | |
| Pump Spacer | 01/01/2014 08:20 | | 4 | 20 | | | 138.0 | FRESH WATER |
| Pump Lead Cement | 01/01/2014 08:27 | | 7 | 61.8 | | | 393.0 | 146 SKS, 12.3 PPG, 2.38 FT3/SK, 13.75 GAL/SK, SETUP TIME 2:58 HRS AT 70 BC |
| Pump Tail Cement | 01/01/2014 08:37 | | 7 | 60 | | | 387.0 | 160 SKS, 12.8 PPG, 2.11 FT3/SK, 11.75 GAL/SK, SETUP TIME 1:51 HRS AT 70 BC |
| Shutdown | 01/01/2014 08:46 | | | | | | | |
| Drop Plug | 01/01/2014 08:49 | | | | | | | |
| Pump Displacement | 01/01/2014 08:49 | | 10 | 76.5 | | | 636.0 | |
| Slow Rate | 01/01/2014 08:59 | | 2 | 10 | | | 313.0 | |
| Bump Plug | 01/01/2014 09:03 | | | | | | | CIRCULATED 20 BBLS/ 47 SKS |
| Check Floats | 01/01/2014 09:05 | | | | | | | FLOATS HELD/ 1 BBLS FLOW BACK TO DISPLACEMENT TANK |
| End Job | 01/01/2014 09:06 | | | | | | | |
| Post-Job Safety Meeting (Pre Rig-Down) | 01/01/2014 09:10 | | | | | | | |
| Rig-Down Completed | 01/01/2014 10:30 | | | | | | | |
| Depart Location Safety Meeting | 01/01/2014 10:45 | | | | | | | |
| Crew Leave Location | 01/01/2014 11:00 | | | | | | | |
| Other | 01/01/2014 11:01 | | | | | | | THANK YOU FOR YOUR BUSINESS FROM JAVIER CASTILLO AND CREW |

WPX RWF 324-25 SURFACE



— DH Density (ppg)
 — Comb Pump Rate (bbl/min)
 — PS Pump Press (psi)
 — Pump Stg Tot (bbl)

- Start Job 8.78;0;26;15.1 • Test Lines 8.91;0;3709;2.2 • Pump Tail Cement 12.82;6.7;289;3.3 • Pump Displacement 11.41;0.8;22;0 • Check Floats 8.33;0;81;85.5
- Fill Lines 8.73;0;-1;0 • Pump Water Spacer 8.69;2.3;31;0.3 • Shutdown 11.71;0;60;62.4 • Slow Rate 8.32;2.1;337;78.2 • End Job 8.33;0;35;85.5
- Stall Out 8.82;0;2187;2.1 • Pump Lead Cement 11.87;3.9;151;1.3 • Drop Plug 11.43;0;22;62.4 • Bump Plug 8.35;1.7;661;85.5

▼ HALLIBURTON | iCem® Service

Created: 2014-01-01 06:33:12, Version: 2.0.606

[Edit](#)

Customer : WPX ENERGY ROCKY MOUNTAIN LLC-EBUS

Job Date : 1/1/2014 6:34:54 AM


Well : RWF 324-25

Representative: LUKE HUBBARD

Sales Order #: 901010585

ELITE #7 : J. CASTILLO / DAN SINCLAIR

WPX RWF 324-25 SURFACE



HALLIBURTON

Water Analysis Report

Company: WPX
Submitted by: JAVIER CASTILLO
Attention: J.Trout
Lease: RWF
Well #: 324-25

Date: 1/1/2014
Date Rec.: 1/1/2014
S.O.#: 901010585
Job Type: SURFACE

| | | |
|-----------------------------|--------------|-------------------|
| Specific Gravity | <i>MAX</i> | 1 |
| pH | <i>8</i> | 7 |
| Potassium (K) | <i>5000</i> | 200 Mg / L |
| Calcium (Ca) | <i>500</i> | 120 Mg / L |
| Iron (FE2) | <i>300</i> | 0 Mg / L |
| Chlorides (Cl) | <i>3000</i> | 0 Mg / L |
| Sulfates (SO ₄) | <i>1500</i> | 200 Mg / L |
| Chlorine (Cl ₂) | | 0 Mg / L |
| Temp | <i>40-80</i> | 75 Deg |
| Total Dissolved Solids | | 510 Mg / L |

Respectfully: JAVIER CASTILLO

Title: CEMENTING SUPERVISOR

Location: Grand Junction, CO

NOTICE:

This report is limited to the described sample tested. Any person using or relying on this report agrees that Halliburton shall not be liable for any loss or damage whether due to act or omission resulting from such report or

| | | |
|--|--|---|
| Sales Order #: 901010585 | Line Item: 10 | Survey Conducted Date: 1/1/2014 |
| Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS | | Job Type (BOM): CMT SURFACE CASING BOM |
| Customer Representative: LUKE HUBBARD | | API / UWI: (leave blank if unknown) AFEYK2MVPIKDORQFAAA |
| Well Name: RWF | | Well Number: 324-25 |
| Well Type: Development Well | Well Country: United States of America | |
| H2S Present: | Well State: Colorado | Well County: Garfield |

Dear Customer,

We hope that you were satisfied with the service quality of this job performed by Halliburton. It is the aim of our management and service personnel to deliver equipment and service of a standard unmatched in the service sector of the energy industry.

Please take the time to let us know if our performance met with your satisfaction. Please be as critical as possible to ensure we constantly improve our service. Your comments are of great value to us and are intended for the exclusive use of Halliburton.

CUSTOMER SATISFACTION SURVEY

| CATEGORY | CUSTOMER SATISFACTION RESPONSE | |
|-------------------------|--|------------------------------|
| Survey Conducted Date | The date the survey was conducted | 1/1/2014 |
| Survey Interviewer | The survey interviewer is the person who initiated the survey. | FRANCISCO CASTILLO (HB85312) |
| Customer Participation | Did the customer participate in this survey? (Y/N) | Yes |
| Customer Representative | Enter the Customer representative name | LUKE HUBBARD |
| HSE | Was our HSE performance satisfactory? Circle Y or N | Yes |
| Equipment | Were you satisfied with our Equipment? Circle Y or N | Yes |
| Personnel | Were you satisfied with our people? Circle Y or N | Yes |
| Customer Comment | Customer's Comment | GOOD JOB |

| |
|---------------------------|
| CUSTOMER SIGNATURE |
|---------------------------|

| | | |
|--|--|---|
| Sales Order #: 901010585 | Line Item: 10 | Survey Conducted Date: 1/1/2014 |
| Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS | | Job Type (BOM): CMT SURFACE CASING BOM |
| Customer Representative: LUKE HUBBARD | | API / UWI: (leave blank if unknown) AFEYK2MVPIKDORQFAAA |
| Well Name: RWF | | Well Number: 324-25 |
| Well Type: Development Well | Well Country: United States of America | |
| H2S Present: | Well State: Colorado | Well County: Garfield |

KEY PERFORMANCE INDICATORS

| General | |
|-----------------------------------|----------|
| Survey Conducted Date | 1/1/2014 |
| The date the survey was conducted | |

| Cementing KPI Survey | |
|---|-------------------------|
| Type of Job | 0 |
| Select the type of job. (Cementing or Non-Cementing) | |
| Select the Maximum Deviation range for this Job | Vertical |
| What is the highest deviation for the job you just completed? This may not be the maximum well deviation. | |
| Total Operating Time (hours) | 6 |
| Total Operating Hours Including Rig-up, Pumping, Rig-down. Enter in decimal format. | |
| HSE Incident, Accident, Injury | No |
| HSE Incident, Accident, Injury. This should be recordable incidents only. | |
| Was the job purpose achieved? | Yes |
| Was the job delivered correctly as per customer agreed design? | |
| Operating Hours (Pumping Hours) | 1 |
| Total number of hours pumping fluid on this job. Enter in decimal format. | |
| Customer Non-Productive Rig Time (hrs) | 0 |
| Lost time due to Halliburton in the start, execution, or completion of an ordered service or product, or delays in a follow-on service. Enter in decimal format. 0 if none. | |
| Type of Rig Classification Job Was Performed | Drilling Rig (Portable) |
| Type Of Rig (classification) Job Was Performed On | |
| Number Of JSAs Performed | 5 |
| Number Of Jsas Performed | |
| Number of Unplanned Shutdowns | 0 |
| Unplanned shutdown is when injection stops for any period of time. | |
| Was this a Primary Cement Job (Yes / No) | Yes |

| | | |
|--|--|---|
| Sales Order #: 901010585 | Line Item: 10 | Survey Conducted Date: 1/1/2014 |
| Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS | | Job Type (BOM): CMT SURFACE CASING BOM |
| Customer Representative: LUKE HUBBARD | | API / UWI: (leave blank if unknown) AFEYK2MVPIKDORQFAAA |
| Well Name: RWF | | Well Number: 324-25 |
| Well Type: Development Well | Well Country: United States of America | |
| H2S Present: | Well State: Colorado | Well County: Garfield |

| | |
|--|-----|
| Primary Cement Job= Casing job, Liner job, or Tie-back job. | |
| Did We Run Wiper Plugs? Did We Run Top And Bottom Casing Wiper Plugs? | Top |
| Mixing Density of Job Stayed in Designed Density Range (0-100%) Density Range defined as +/- .20 ppg. Calculation: Total BBLs cement mixed at designed density divided by total BBLs of cement multiplied by 100 | 90 |
| Was Automated Density Control Used? Was Automated Density Control (ADC) Used ? | Yes |
| Pump Rate (percent) of Job Stayed At Designed Pump Rate Pump Rate range defined as +/- 1bbl/min. Calculation: Total BBLs of fluid pumped at the designed rate divided by Total BBLs of fluid pumped, multiplied by 100 | 95 |
| Nbr of Remedial Sqz Jobs Rqd - Competition Number Of Remedial Squeeze Jobs Required After Primary Job Performed By Competition | 0 |
| Nbr of Remedial Plug Jobs Rqd - HES Number Of Remedial Plug Jobs Needed After Primary Plug Pumped By HES | 0 |
| Nbr of Remedial Sqz Jobs Rqd - HES Number Of Remedial Squeeze Jobs Required After Primary Job Performed By HES | 0 |