

**FORM  
INSP**

Rev  
05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
04/01/2014

Document Number:  
668301050

Overall Inspection:  
**Unsatisfactory**

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	241058	318298	JOHNSON, RANDELL	2A Doc Num:	

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_

Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Fogel, Heather		hfogel@nobleenergyinc.com	

**Compliance Summary:**

QtrQtr: NWNE Sec: 13 Twp: 1N Range: 68W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/21/2013	668300399	IJ	SI	Satisfactory	P		No
08/10/2012	667600656	IJ	IJ	Satisfactory	P		No
08/15/2011	200318979	RT	SI	Satisfactory			No
08/24/2010	200267992	MI	SI	Satisfactory			No
07/10/2009	200214806	RT	AC	Satisfactory			No
08/21/2008	200194202	RT	AC	Satisfactory			No
10/10/2007	200120277	RT	AC	Satisfactory			No
07/12/2007	200114652	RT	AC	Satisfactory		Pass	No
07/06/2006	200093871	RT	AC	Satisfactory		Pass	No
06/15/2005	200073075	MI	AC	Satisfactory		Pass	No
06/02/2004	200055187	RT	AC	Satisfactory		Pass	No
03/12/2003	200035977	RT	AC	Satisfactory		Pass	No
04/04/2002	200025523	RT	AC	Satisfactory		Pass	No
04/27/2001	200016396	RT	AC	Satisfactory		Pass	No
06/23/2000	200007369	MI	AC	Satisfactory		Pass	No
05/10/1995	500163476						
10/05/1994	500163475		AC			Pass	No

**Inspector Comment:**

\_\_\_\_\_

**Related Facilities:**

\_\_\_\_\_

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150128	UIC DISPOSAL	AC	06/26/1984		-	EMERY 31-13 #1	AC
241058	WELL	IJ	07/15/2006	OW	123-08846	EMERY 31-13 (1-68) 1	SI

**Equipment:** Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Signs/Marker:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
CONTAINERS	Unsatisfactory	Barrel inside berm does not have the required contents signage	Install sign to comply with rule 210.	05/01/2014
BATTERY	Satisfactory			
CONTAINERS	Unsatisfactory	LPG tank does not have the required contents and NFPA signage	Install sign to comply with rule 210.	05/01/2014
TANK LABELS/PLACARDS	Unsatisfactory	Two fiberglass tanks do not have contents signage	Install sign to comply with rule 210.	05/10/2014

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory	Debris pile next to wellhead/See photos on last page of document	Remove debris	05/01/2014

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
Crude Oil	Tank	<= 5 bbls	Remove or remediate contaminated soil at the back of south fiberglass tank/See photos on last page of document	05/01/2014

Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	Pipe fencing		

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
OTHER	2	400 BBLS	FIBERGLASS AST	40.056370,-104.948840
S/U/V:	Unsatisfactory		Comment: Contents unknown - no signage/Tanks not painted according to regulations/See photos on last page of document	
Corrective Action:	Paint tanks according COGCC Rule 804			Corrective Date: 05/01/2014

**Paint**

Condition	Inadequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Corrective Action				Corrective Date
Comment				

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST	40.056370,-104.948840
S/U/V:	Unsatisfactory		Comment: South crude oil tank not painted according to regulations/See photos on last page of document	
Corrective Action:	Paint tank according to COGCC Rule 804			Corrective Date: 05/01/2014

**Paint**

Condition	Inadequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Corrective Action				Corrective Date
Comment				

**Venting:**

Yes/No	Comment
NO	

**Flaring:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 241058

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/UV:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/UV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/UV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 241058 Type: WELL API Number: 123-08846 Status: IJ Insp. Status: SI

**Underground Injection Control**

UIC Violation: \_\_\_\_\_

Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**

Inj./Tube: Pressure or inches of Hg 0 psi  
(e.g. 30 psig or -30" Hg)

Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
Inj Zone: SUSX

TC: Pressure or inches of Hg \_\_\_\_\_

Previous Test Pressure \_\_\_\_\_ Last MIT: 08/24/2010

Brhd: Pressure or inches of Hg 0 psi

Previous Test Pressure \_\_\_\_\_ AnnMTRReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Method of Injection: GRAVITY FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass  
 Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment:

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment:

Corrective Action:  Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Other	Pass	Other	Pass			Vegetation
Gravel	Pass	Gravel	Pass			

S/U/V: Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits:  NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668301051	Noble - Emery 31-13 (1-68) 1 (123-08846) - 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312730">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312730</a>
668301052	Noble - Emery 31-13 (1-68) 1 (123-08846) - 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312731">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312731</a>
668301053	Noble - Emery 31-13 (1-68) 1 (123-08846) - 3	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312732</a>
668301054	Noble - Emery 31-13 (1-68) 1 (123-08846) - 4	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312733">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312733</a>
668301055	Noble - Emery 31-13 (1-68) 1 (123-08846) - 5	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312734">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312734</a>
668301056	Noble - Emery 31-13 (1-68) 1 (123-08846) - 6	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312735">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312735</a>
668301057	Noble - Emery 31-13 (1-68) 1 (123-08846) - 7	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312736">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312736</a>
668301058	Noble - Emery 31-13 (1-68) 1 (123-08846) - 8	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312737">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312737</a>
668301059	Noble - Emery 31-13 (1-68) 1 (123-08846) - 9	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312738">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312738</a>
668301060	Noble - Emery 31-13 (1-68) 1 (123-08846) - 10	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312739">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312739</a>
668301061	Noble - Emery 31-13 (1-68) 1 (123-08846) - 11	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312740">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312740</a>
668301062	Noble - Emery 31-13 (1-68) 1 (123-08846) - 12	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312741">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3312741</a>