

**FORM INSP**  
Rev 05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
04/08/2014

Document Number:  
668301122

Overall Inspection:

**Violation**

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	<u>239579</u>	<u>317615</u>	<u>JOHNSON, RANDELL</u>	2A Doc Num:	

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
ELLSWORTH, STUART		stuart.ellsworth@state.co.us	
Group, Email		cogcc.djinspections@encana.com	Group Email
House, Chris	303-774-3972	larry.house@encana.com	Strategic Projects Advisor

**Compliance Summary:**

QtrQtr: NENE Sec: 18 Twp: 1N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/27/2008	200198102	PR	PR	<b>Unsatisfactory</b>			Yes
12/19/2003	200047853	PR	PR	Satisfactory		Pass	No
08/16/2000	200008848	PR	PR	Satisfactory		Pass	No
01/12/1996	500161150	PR	PR			Pass	No

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
239579	WELL	PR	09/10/1997	GW	123-07367	HINGLEY FARMS 1	TA	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Signs/Marker:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory			
BATTERY	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TRASH	Unsatisfactory	Trash on location/See attached photos on last page of document	Remove trash	05/08/2014
UNUSED EQUIPMENT	Unsatisfactory	Unused equipment on location/See attached photos on last page of document	Remove unused equipment	05/08/2014

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
Other		<= 5 bbls	Remove or remediate area of stained soil immediately east of old unused meter run house/See attached photo on last page of document	05/08/2014
Other		<= 5 bbls	Remove or remediate areas of stained soil 60 feet north of wellhead/See attached photo on last page of document	05/08/2014
Other	WELLHEAD	<= 5 bbls	Remove or remediate areas of stained soil in the immediate area of the wellhead/See attached photo on last page of document	05/08/2014
Other		<= 5 bbls	Remove or remediate areas of stained soil 15 feet south of wellhead/See attached photo on last page of document	05/08/2014

Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	Chain-link fencing		
TANK BATTERY	Satisfactory	Chain-link fencing		
SEPARATOR	Satisfactory	Chain-link fencing		

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	1	Satisfactory	Operator check meter on outlet of separator		
Horizontal Heated Separator	1	Satisfactory			

Gas Meter Run	2	Satisfactory	Pipeline meters		
---------------	---	--------------	-----------------	--	--

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS	40.055540,-104.927000

S/U/V: Satisfactory Comment: 150 bbls

Corrective Action: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

**Paint**

Condition Adequate

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action \_\_\_\_\_ Corrective Date \_\_\_\_\_

Comment \_\_\_\_\_

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST	40.055540,-104.927000

S/U/V: Satisfactory Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

**Paint**

Condition Adequate

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action \_\_\_\_\_ Corrective Date \_\_\_\_\_

Comment \_\_\_\_\_

**Venting:**

Yes/No	Comment
NO	

**Flaring:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 239579

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 239579 Type: WELL API Number: 123-07367 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

S/V:  CA Date:

CA: Well must be either:  
1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production or  
2) Be properly plugged and abandoned.  
3) A sundry requesting continued temporarily abandoned status should be submitted to Stuart Ellsworth at the COGCC within thirty (30) days of receipt of this report - the sundry should detail the plan for the future operation of the well and the way the well is closed to the atmosphere. Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Comment: Wellhead equipment is disconnected and well is temporarily abandoned/incapable of production/See attached photo on last page of document

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment:

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			Vegetation
Gravel	Pass	Gravel	Pass			

Compaction	Pass	Compaction	Pass		
S/U/V: <u>Satisfactory</u>		Corrective Date: _____			
Comment: _____					
CA: _____					
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT					

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668301125	Encana - Hingley Farms 1 (123-07367) - 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316893">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316893</a>
668301127	Encana - Hingley Farms 1 (123-07367) - 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316894">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316894</a>
668301128	Encana - Hingley Farms 1 (123-07367) - 3	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316895">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316895</a>
668301129	Encana - Hingley Farms 1 (123-07367) - 4	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316896">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316896</a>
668301130	Encana - Hingley Farms 1 (123-07367) - 5	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316897">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316897</a>
668301131	Encana - Hingley Farms 1 (123-07367) - 6	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316898">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316898</a>
668301132	Encana - Hingley Farms 1 (123-07367) - 7	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316899">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316899</a>
668301133	Encana - Hingley Farms 1 (123-07367) - 8	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316900">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316900</a>
668301134	Encana - Hingley Farms 1 (123-07367) - 9	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316901">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316901</a>
668301135	Encana - Hingley Farms 1 (123-07367) - 10	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316902">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316902</a>
668301136	Encana - Hingley Farms 1 (123-07367) - 11	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316903">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316903</a>
668301137	Encana - Hingley Farms 1 (123-07367) - 12	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316904">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316904</a>
668301138	Encana - Hingley Farms 1 (123-07367) - 13	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316905">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316905</a>
668301139	Encana - Hingley Farms 1 (123-07367) - 14	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316906">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316906</a>
668301140	Encana - Hingley Farms 1 (123-07367) - 15	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316907">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316907</a>
668301141	Encana - Hingley Farms 1 (123-07367) - 16	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316908">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316908</a>
668301142	Encana - Hingley Farms 1 (123-07367) - 17	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316909">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316909</a>
668301143	Encana - Hingley Farms 1 (123-07367) - 18	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316910">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316910</a>
668301144	Encana - Hingley Farms 1 (123-07367) - 19	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316911">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3316911</a>