

<b>FORM INSP</b> <small>Rev 05/11</small>	<b>State of Colorado</b>				DE	ET	OE	ES
	<b>Oil and Gas Conservation Commission</b>				Inspection Date: <u>04/08/2014</u>			
<small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>								

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	229125	314611	BROWNING, CHUCK	2A Doc Num:	

Document Number:  
668402008

Overall Inspection:  
**Violation**

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_

Name of Operator: CHEVRON PRODUCTION COMPANY

Address: 100 CHEVRON RD

City: RANGELY State: CO Zip: 81648

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	Regulatory Specialist
KOEHLER, BOB		bob.koehler@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

**Compliance Summary:**

QtrQtr: NWSE Sec: 27 Twp: 2N Range: 102W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/25/2014	673500849	PR	PR	Satisfactory			No
02/10/2014	673500582	PR	PR	Satisfactory	P		No
10/27/2013	673500022	PR	PR	Satisfactory	P		No
05/17/2002	200027488	ID	SI	Satisfactory		Pass	No
11/07/2000	200011303	ID	TA	Unsatisfactory		Fail	Yes
01/04/2000	200004848	ID	SI	Satisfactory		Pass	No
04/10/1997	500156859	PR	SI			Pass	No

**Inspector Comment:**

This well is in violation of COGCC Rules 326.a for MIT of UIC (Underground Injection Control). The operator is required to contact COGCC Engineering Staff within 10 days of the date of this inspection report for approval of a schedule for either performing an MIT, or Plugging and Abandoning the well. If the MIT option is selected the well must pass an MIT to become compliant. The operator must provide ten (10) days written notice, via Form 42, to the field inspector prior to the MIT as required by Rule. If the MIT is not completed prior to a date approved by Engineering Staff or the well fails the MIT this matter will be referred to COGCC Enforcement Staff for formal proceedings. It will be to the operator's benefit to correct the violation immediately, though completion of required corrective action(s) will not eliminate the imposition of a penalty for past noncompliance

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
117285	PIT		09/23/1999		-	RANGELY WEBER SAND UNIT 29	<input type="checkbox"/>
229125	WELL	PR			103-06208	UNION PACIFIC 32-27	<input checked="" type="checkbox"/>

**Equipment:** Location Inventory

---

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			
Main	Satisfactory			

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

**Equipment:**

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Deadman # & Marked	4	Satisfactory			

**Venting:**

Yes/No	Comment

**Flaring:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 229125

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 229125 Type: WELL API Number: 103-06208 Status: PR Insp. Status: SI

**Underground Injection Control**

UIC Violation: Failed MIT Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: WEBR

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 06/11/2009

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTRReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: 5 Year Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: Fail Leak Type: \_\_\_\_\_

Comment: Failed UIC-MIT. Pressure well to 1200 psi . Failed to hold pressure for 15 min.

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass  
 1003c. Compacted areas have been cross ripped? Pass  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass  
 Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	SI	Pass	

S/U/V: Satisfactory                      Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT