

# CEMENT JOB REPORT



CUSTOMER BAYSWATER EXPLORATION I		DATE 08-APR-14	F.R. # 10011058852	SERV. SUPV. RYAN R STEVENS											
LEASE & WELL NAME CUNDALL #5-12 - API 05001094920000		LOCATION 12-1S-68W		COUNTY-PARISH-BLOCK Adams Colorado											
DISTRICT Brighton		DRILLING CONTRACTOR RIG # W/O		TYPE OF JOB Squeeze-Perforation											
SIZE & TYPE OF PLUGS		LIST-CSG-HARDWARE		MECHANICAL BARRIERS		MD	TVD	HANGER TYPES	MD	TVD					
None		NA-Squeeze		None		0	0	None	0	0					
		No Shoe													
MATERIALS FURNISHED BY BJ				LAB REPORT NO.				PHYSICAL SLURRY PROPERTIES							
								SACKS OF CEMENT	SLURRY WGT PPG	SLURRY YLD FT <sub>3</sub>	WATER GPS	PUMP TIME HR:MIN	Bbl SLURRY	Bbl MIX WATER	
Fresh Water								0	8.34	0	0		10		
Plug #1								50	15.8	1.15	5.00		10.22	5.95	
Fresh Water								0	8.34	0	0		17.3		
Plug #2				0				0	0	0	00:00		0		
Fresh Water								0	8.34	0	00:00		10		
Fresh Water									8.34				10		
Available Mix Water		150 Bbl.		Available Displ. Fluid		150 Bbl.		TOTAL		57.52		5.95			
HOLE			TBG-CSG-D.P.						COLLAR DEPTHS						
SIZE	% EXCESS	DEPTH	ID	OD	WGT.	CSG	TYPE	MD	TVD	GRADE	SHOE	FLOAT	STAGE		
8	0	1181	4	4.5	11.6	CSG		1181	1181		0	0	0		
LAST CASING			PKR-CMT RET-BR PL-LINER			PERF. DEPTH			TOP CONN		WELL FLUID				
ID	OD	WGT	TYPE	MD	TVD	BRAND & TYPE		DEPTH	TOP	BTM	SIZE	THREAD	TYPE	WGT.	
						NO LINER					2	1502	FRESH WATER	8.34	
DISPL. VOLUME		DISPL. FLUID		CAL. PSI	CAL. MAX PSI	OP. MAX	MAX TBG PSI		MAX CSG PSI		MIX WATER				
VOLUME	UOM	TYPE		WGT.	BUMP PLUG	TO REV.	SQ. PSI	RATED	Operator	RATED	Operator				
17.3	BBLs	Fresh Water		8.34	0	0	0	0	0	6224	3000	Transport			
		Fresh Water		8.34											
Circulation Prior to Job															
Circulated Well: Rig <input checked="" type="checkbox"/> BJ <input type="checkbox"/>				Circulation Time: 0				Circulation Rate: 0 BPM							
Mud Density In: 8.34 LBS/G				Mud Density Out: 8.34 LBS/GAL				PV & YP Mud In: 0				PV & YP Mud Out: 0			
Gas Present: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/>				Units:				Solids Present at End of Circulation: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/>							
Displacement And Mud Removal															
Displaced By: Rig <input type="checkbox"/> BJ <input checked="" type="checkbox"/>				Amount Bled Back After Job: 0 BBLs											
Returns During Job: <input type="checkbox"/> NONE <input type="checkbox"/> PARTIAL <input checked="" type="checkbox"/> FULL				Method Used to Verify Returns: Visual											
Cement Returns at Surface: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				Were Returns Planned at Surface: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES											
Pipe Movement: <input type="checkbox"/> ROTATION <input type="checkbox"/> RECIPROCATION <input checked="" type="checkbox"/> NONE <input type="checkbox"/> UNABLE DUE TO STUCK PIPE															
Centralizers: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Quantity:				Type: <input type="checkbox"/> BOW <input type="checkbox"/> RIGID							
Job Pumped Through: <input type="checkbox"/> CHOKE MANIFOLD <input type="checkbox"/> SQUEEZE MANIFOLD <input type="checkbox"/> MANIFOLD <input checked="" type="checkbox"/> NO MANIFOLD															
Plugs															
Number of Attempts by BJ: 0				Competition: 0				Wiper Balls Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES Quantity:							
Plug Catcher Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Parabow Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES											
Was There a Bottom: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Top of Plug: 0 FT				Bottom of Plug: 0 FT							
Squeezes (Update Original Treatment Report for Primary Job)															
BLOCK SQUEEZE <input type="checkbox"/>				SHOE SQUEEZE <input type="checkbox"/>				TOP OF LINER SQUEEZE <input type="checkbox"/>				PLANNED <input type="checkbox"/> UNPLANNED <input type="checkbox"/>			
Liner Packer: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Bond Log: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				PSI Applied: 0				Fluid Weight: 0 LBS/GAL			
Casing Test (Update Original Treatment Report for Primary Job)															
Casing Test Pressure: 0 PSI				With 0 LBS/GAL Mud				Time Held: 00 Hours 00 Minutes							
EXPLANATION: TROUBLE SETTING TOOL, RUNNING CSG, ETC. PRIOR TO CEMENTING: None															

## CEMENT JOB REPORT



### Shoe Test (Update Original Treatment Report for Primary Job)

Depth Drilled out of Shoe: 0 FT      Target EMW: 0 LBS/GAL      Actual EMW: 0 LBS/GAL

Number of Times Tests Conducted: 0      Mud Weight When Test was Conducted: 0 LBS/GAL

Problems Before Job (I.E. Running Casing, Circulating Well, ETC)  
None

Problems During Job (I.E. Lost Returns, Equipment Failure, Bulk Delivery, Foaming, ETC)  
None

Problems After Job (I.E. Gas at Surface, Float Equipment Failed, ETC)  
None

PRESSURE/RATE DETAIL						EXPLANATION		
TIME HR:MIN.	PRESSURE - PSI		RATE BPM	Bbl. FLUID PUMPED	FLUID TYPE	SAFETY MEETING: BJ CREW <input checked="" type="checkbox"/> CO. REP. <input checked="" type="checkbox"/>		
	PIPE	ANNULUS				TEST LINES 3740 PSI		
						CIRCULATING WELL - RIG <input checked="" type="checkbox"/> BJ <input type="checkbox"/>		
08:00	0	0	0	0	N/A	Yard call		
10:16	0	0	0	0	N/A	Time left district		
10:40	0	0	0	0	N/A	Time arrived on location		
11:17	0	0	0	0	N/A	Pre rig up safety meeting		
12:25	0	0	0	0	N/A	Pre job safety meeting		
12:42	3740	0	0	0	WATER	Pressure test		
12:45	5	0	2	8	WATER	Fresh water		
12:50	0	0	2.6	8	CEMENT	Batch up, weigh and pump 50 SXS Class G Neat Cement		
12:59	0	0	2.9	16.5	WATER	Displacement		
13:03	0	0	0	0	N/A	Shut it down Job done		
13:04	0	0	0	0	N/A	Pre rig down safety meeting		
13:40	0	0	0	0	N/A	Tim off location		

BUMPED PLUG	PSI TO BUMP PLUG	TEST FLOAT EQUIP.	BBL.CMT RETURNS/ REVERSED	TOTAL BBL. PUMPED	PSI LEFT ON CSG	SPOT TOP OUT CEMENT	Service Supervisor Signature:
Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	0	Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	0	32.5	0	Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	



Baker Hughes JobMaster Program Version 3.60

Job Number: 10011058852

Customer: Bayswater

Well Name: Cundall 5-12

