

# Chain of Custody Record

TAL-4124-280 (0508)

Sampler ID \_\_\_\_\_  
 Temperature on Receipt \_\_\_\_\_  
 Drinking Water? Yes ☐ No ☐

## TestAmerica

THE LEADER IN ENVIRONMENTAL TESTING

Client Colorado Oil and Gas Cons. Comm  
 Address 1120 Lincoln St #801  
 City Denver State CO Zip Code 80203  
 Project Name and Location (State) Atwood CO  
 Contract/Purchase Order/Quote No. 67505281  
 Project Manager \_\_\_\_\_  
 Telephone Number (Area Code)/Fax Number \_\_\_\_\_  
 Lab Contact \_\_\_\_\_  
 Site Contact \_\_\_\_\_  
 Carrier/Waybill Number \_\_\_\_\_  
 Date \_\_\_\_\_  
 Lab Number \_\_\_\_\_  
 Chain of Custody Number 184258  
 Page \_\_\_\_\_ of \_\_\_\_\_

Sample I.D. No. and Description (Containers for each sample may be combined on one line)	Date	Time	Matrix			Containers & Preservatives						Analysis (Attach list if more space is needed)	Special Instructions/Conditions of Receipt	
			Air	Aqueous	Sed.	Soil	Unpres.	H <sub>2</sub> SO <sub>4</sub>	HNO <sub>3</sub>	HCl	NaOH			ZnAc/NaOH
Atwood 5001	3/11/14	1045	X											
Atwood 5002		1050	X											
Atwood 5003		1055	X											

Possible Hazard Identification	Turn Around Time Required	Non-Hazard	Flammable	Skin Irritant	Poison B	Unknown	Return To Client	Disposal By Lab	Archive For _____ Months	QC Requirements (Specify)

1. Relinquished By	2. Relinquished By	3. Relinquished By
Date <u>3/12/14</u> Time <u>1350</u>	Date <u>3/12/14</u> Time <u>1350</u>	Date <u>3/12/14</u> Time <u>1350</u>

DISTRIBUTION: WHITE - Returned to Client with Report; CANARY - Stays with the Sample; PINK - Field Copy