

INSPECTION #675200004 Please scroll down to view pictures



Weeds in SE corner of separator containment need to be removed.