

Peterson Ridge ##1-20H site visit  
1/21/2014

# Is the red diesel fuel?



White on ground is NOT snow, it is chemical that has come out of broken chem bag



# More chemical



21/01/2014 14:15

Not Snow, appears to be a fibrous material. Blowing around location.



Pile of trash. note liner material; it is all over location and incorporated in the cuttings piles.



# More diesel



# More diesel



# Frac Sand



# North Side of location, pile of cutting and trash



North side of location, no berm on E&P waste, trash blowing around location



“Berm” that was installed since previous visit. Berm is not countinuous and frac tank is sitting in E&P waste.



# Back of frac tank, parked in E&P waste



# Another Frac tank parked in E&P waste



# Cutting trench, delineated cuttings or mud and trash, Freeboard?



# More diesel



# More diesel

