

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/06/2014

Document Number:

673703802

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	204006	320625	Sherman, Susan	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 41550Name of Operator: TYLER ROCKIES EXPLORATION LTDAddress: P O BOX 119City: TYLER State: TX Zip: 75710-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Hall, Dan	(303) 966-9610	dan@energyop.com	
Behrens, Vic	(303) 810-6382	behrens@netecin.net	
Strawn, Mark	930-595-4886	texcomo@sbcglobal.net	

**Compliance Summary:**QtrQtr: SWSE Sec: 29 Twp: 4S Range: 60W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/19/2013	668300383	SI	UN	SATISFACTORY Y	P		No
07/30/2012	667600595	IJ	IJ	SATISFACTORY Y	P		No
08/18/2011	200318974	RT	AC	SATISFACTORY Y			No
08/06/2010	200266117	MI	PR	SATISFACTORY Y			No
04/15/2010	200250386	SR	AC	SATISFACTORY Y			No
08/20/2009	200217007	RT	AC	SATISFACTORY Y			No
08/11/2008	200194198	RT	AC	SATISFACTORY Y			No
07/13/2007	200114646	RT	IO	SATISFACTORY Y		Pass	No
06/20/2006	200093853	RT	SI	SATISFACTORY Y		Pass	No
07/26/2005	200074229	MI	TA	SATISFACTORY Y		Pass	No
08/03/2004	200057558	RT	TA	SATISFACTORY Y		Pass	No
08/19/2003	200042999	RT	TA	SATISFACTORY Y		Pass	No
06/11/2002	200027262	RT	TA	SATISFACTORY Y		Pass	No

Inspector Name: Sherman, Susan

07/11/2001	1065388	RT	TA	<b>ACTION REQUIRED</b>		<b>Fail</b>	Yes
08/02/2000	896120	MI	TA	SATISFACTORY		Pass	No
07/23/1999	500134087	ID	AC			<b>Fail</b>	Yes

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
204006	WELL	SI	04/15/2014	OW	005-06089	PEORIA J-SAND UNIT 27	SI	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	<b>steel panels</b>		

<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	1	SATISFACTORY	<b>pump jack concrete pad</b>		
Deadman # & Marked	4	SATISFACTORY			

<b>Venting:</b>		
Yes/No	Comment	

Inspector Name: Sherman, Susan

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 204006

**Site Preparation:**

Lease Road Adeq.: Pads: Soil Stockpile:

**S/A/V:**

Corrective Action: Date: CDP Num.:

**Form 2A COAs:**

**S/A/V:** **Comment:**

**CA:** **Date:**

**Wildlife BMPs:**

**S/A/V:** **Comment:**

**CA:** **Date:**

**Stormwater:**

**Comment:**

**Staking:**

**On Site Inspection (305):**

**Surface Owner Contact Information:**

Name: Address: Phone Number: Cell Phone:

**Operator Rep. Contact Information:**

Landman Name: Phone Number:

Date Onsite Request Received: Date of Rule 306 Consultation:

Request LGD Attendance:

**LGD Contact Information:**

Name: Phone Number: Agreed to Attend:

**Summary of Landowner Issues:**

**Summary of Operator Response to Landowner Issues:**

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

**Facility**

Facility ID: 204006 Type: WELL API Number: 005-06089 Status: SI Insp. Status: SI

**Underground Injection Control**

UIC Violation: \_\_\_\_\_

Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 08/06/2010

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: 5 Year Tbg psi: vacuum Csg psi: 0 psi BH psi: 55 psi

Insp. Status: Pass

Comment: Initial 339 psi, 5 min 339 psi, 10 min 339 psi, 15 min 335 psi (pumper tapped pipe). Used 225 gals water to fill casing and 5 gals packer fluid. Gravity fed. Form 21 attached.

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: open rangeland

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Inspector Name: Sherman, Susan

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: Bare spot south of REA pole on access road (see attached photo).

Overall Interim Reclamation

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

#### **Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Inspector Name: Sherman, Susan

Gravel	Pass	Gravel	Pass			
--------	------	--------	------	--	--	--

S/A/V: SATISFACTOR      Corrective Date: \_\_\_\_\_  
Y \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

### Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673703828	TREX Peoria Unit #27 IJ well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3359996">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3359996</a>
673703829	TREX Peoria Unit #27 IJ well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3359997">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3359997</a>
673703830	TREX Peoria Unit #27 IJ well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3359998">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3359998</a>
673703832	TREX Peoria Unit #27 IJ well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3359999">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3359999</a>
673703833	TREX Peoria Unit #27 MIT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3360000">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3360000</a>