

Job Information

Request ID	2005745	Rig Name		Date	15/MAY/2014
Submitted By	Nathan Barnum	Job Type	Fracturing/Stimulation	Well	Hunter Mesa
Customer	Encana	Location			

Well Information

Formation	Unknown	Depth MD		BHST	
Pressure		Depth TVD		Cool Down Temperature	

Results For Request ID 2005745

Water Analysis

Tank Number/Source	W221
Specific Gravity	1.010
pH	7.54
Chlorides (mg/L)	7074
Calcium (mg/L)	590
Magnesium (mg/L)	140
Dissolved Iron (mg/L)	0.7
Potassium (mg/L)	75
Bicarbonates (mg/L)	1410
Carbonates (mg/L)	0
Hydroxides (mg/L)	0
Sulfates (mg/L)	0
Sodium (mg/L)	4124
TDS (mg/L)	13200
Rw Resistivity (Ohms-Meter)	0.520
Temperature (°F)	71

This report is the property of Halliburton Energy Services and neither it nor any part thereof, nor a copy thereof, is to be published or disclosed without first securing the expressed written approval of Halliburton. It may however be used in the course of regular business operations by any person or concern receiving such report from Halliburton. This report is for information purposes only and the content is limited to the sample described. Halliburton makes no warranties, expressed or implied, as to the accuracy of the contents or results. Any user of this report agrees Halliburton shall not be liable for any loss or damage regardless of cause, including any act or omission of Halliburton, resulting from the use hereof.