

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400624293

Date Received:

06/11/2014

Spill report taken by:

Spencer, Stan

Spill/Release Point ID:

437551

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC	OGCC Operator No: 96850	<b>Phone Numbers</b>
Address: 1001 17TH STREET - SUITE #1200		Phone: (970) 6832295
City: DENVER	State: CO	Zip: 80202
Contact Person: Karolina Blaney		Mobile: (970) 2859573
		Email: karolina.blaney@wpxenergy.com

### INITIAL SPILL/RELEASE REPORT

Initial Report Date: 06/04/2014 Date of Discovery: 06/04/2014 Spill Type: Historical Release

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR SENW SEC 19 TWP 2S RNG 98W MERIDIAN 6

Latitude: 39.863315 Longitude: -108.436616

Municipality (if within municipal boundaries): County: RIO BLANCO

#### Reference Location:

Facility Type: TANK BATTERY ☐ Well API No. (if the reference facility is well) 05- -

☒ Facility ID (if not a well) 422672

☐ No Existing Facility ID

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=5 and <10

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

#### Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: warm, dry, sunny

Surface Owner: FEE Other(Specify):

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The Mautz Ranch water receiving tank farm is being upgraded and when the tanks and the liner were removed, a historical impact to soil was discovered. The cause of this release is unknown. The total volume is estimated to be approximately 7bbls.

COGCC Comment Only:

List Agencies and Other Parties Notified:

### OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
6/4/2014	COGCC	Stan Spencer	970-625-2497	initial Form 19
6/4/2014	County	Mark Sprague	970-878-9584	Email
6/4/2014	Fire Department	Steve Allen	970-824-1682	Email
6/4/2014	Public Health	Jeremy Simmons	970-878-9526	Email
6/4/2014	Sheriff	Si Woodruff	970-878-9620	Email

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 06/10/2014		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	7	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet):		25	Width of Impact (feet): 16
Depth of Impact (feet BGS):		2	Depth of Impact (inches BGS):
How was extent determined?			
By field measurements and mapping with a Trimble GPS unit.			

Soil/Geology Description:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Karolina Blaney

Title: Environmental Specialist Date: 06/11/2014 Email: karolina.blaney@wpenergy.com

### **Attachment Check List**

**Att Doc Num**      **Name**

400624310	SITE MAP
-----------	----------

Total Attach: 1 Files

### **General Comments**

**User Group**      **Comment**      **Comment Date**

--	--	--

Total: 0 comment(s)