

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/12/2014

Document Number:

663903317

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334154	334154	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
YOKLEY, BILL		bill.yokley@state.co.us	
Insp., General	970-285-2665	cogcc.inspections@encana.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Compliance Summary:QtrQtr: SWSW Sec: 13 Twp: 8S Range: 96W**Inspector Comment:**No evidence of AL wells**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
281118	WELL	PR	08/01/2007	GW	077-08958	FEDERAL 13-13 (OM13)	PR	<input type="checkbox"/>
284855	WELL	AL	07/20/2010	LO	077-09079	FEDERAL 14-16 (OM13)	AL	<input checked="" type="checkbox"/>
284856	WELL	AL	06/06/2011	LO	077-09078	FEDERAL 13-12 (OM13)	AL	<input checked="" type="checkbox"/>
284857	WELL	AL	06/06/2011	LO	077-09077	FEDERAL 13-14 (OM13)	AL	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	Comment			
Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Predrill				
Location ID: 334154				
Site Preparation:				
Lease Road Adeq.:		Pads:	Soil Stockpile:	
S/A/V:				
Corrective Action:		Date:	CDP Num.:	
Form 2A COAs:				
S/A/V:	Comment:			
CA:				Date:
Wildlife BMPs:				
S/A/V:	Comment:			
CA:				Date:
Stormwater:				
Comment:				
Staking:				
On Site Inspection (305):				
Surface Owner Contact Information:				
Name:		Address:		
Phone Number:		Cell Phone:		
Operator Rep. Contact Information:				
Landman Name:		Phone Number:		
Date Onsite Request Received:		Date of Rule 306 Consultation:		
Request LGD Attendance:				
LGD Contact Information:				
Name:		Phone Number:	Agreed to Attend:	
Summary of Landowner Issues:				
Summary of Operator Response to Landowner Issues:				
Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:				
Facility				

Inspector Name: LONGWORTH, MIKE

Facility ID:	284855	Type:	WELL	API Number:	077-09079	Status:	AL	Insp. Status:	AL
Facility ID:	284856	Type:	WELL	API Number:	077-09078	Status:	AL	Insp. Status:	AL
Facility ID:	284857	Type:	WELL	API Number:	077-09077	Status:	AL	Insp. Status:	AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

Inspector Name: LONGWORTH, MIKE

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date	
No evidence of AL wells	longworm	06/12/2014	