

API: 123_13665

06/04/2014 Site Pictures (6 total)



View of Pad (1)



Erosion and channeling



Erosion and sediment off-site



Erosion and rilling



Bare spots on-site



Failed BMPs now debris