Cover Data

Date: 6/5 Inspected By: Goodwin / Arthur

Location: API # 123-12578

Transect #/disturbed/Ref	(100 PTS)							
Transect Orientation and first photo, degrees								
Photo Midpoint (2)	✓							
End transect	✓							
Photo other								
Photo other								
Photo other								
Aspect/Slope								
	1st Hit	2nd	1st Hit	2nd	1st Hit	2nd	1st Hit	2nd
Litter	☒ :	11						
Bare Soil	☒☒☒☒:	45	AREAS: (4'x10'x5')					
Rock	: :	9						
Total Weeds								
Total Desirable Species								
80% Check		✓						
Species		40						
BON dac								
RAS ~~SOM~~ SMI	☒ LS	17						
SPH COC	: :	4						
Buffalo	☒ : :	14						
SPO CUY	:	2						
FOXTAIL	:	2						
TUMBLE GRASS	.	1						

Cover Data

Date: 6/5 Inspected By: Arthur / Gowdy

Location: API # 123-12578

Transect #/disturbed/Ref	(100 PTS)							
Transect Orientation and first photo, degrees								
Photo Midpoint (2)	✓							
End transect	✓							
Photo other								
Photo other								
Photo other								
Aspect/Slope								
	1st Hit	2nd	1st Hit	2nd	1st Hit	2nd	1st Hit	2nd
Litter	⊠ ··	12						
Bare Soil	⊠ ··	13						
Rock								
Total Weeds								
Total Desirable Species								
80% Check								
Species		75						
AGR SMI	⊠⊠	20						
BOU dac	⊠⊠⊠⊠	46						
LAC SER	:	2						
STICKWEED	·	1						
UPLAND CAREX	··	3						
SHP COC	··	3						
SPC PRESENT								
6 WEEK FESCUE								
MEL OFF								
PLANTAGO SP.								
OXITUPIS SP.								
NATIVE COMPOSITE								