

API: 123\_12579

06/05/2014 Site Pictures (total)



Site Entrance



View of reclaimed pad





Oil soaked soil (5'x5' area approximately) view 1



Oil soaked soil (5'x5' area approximately) view 1





Discolored soil (12' 12' area approximately)



Inside Transect Beginning





Inside Transect Midpoint ground cover





Inside Transect Midpoint Perpendicular view 1





Inside Transect Midpoint Perpendicular view 2






Inside Transect End view





Outside Transect



Outside Transect Beginning





Outside Transect Midpoint groundcover





Outside Transect Midpoint parallel view 1





Outside Transect Midpoint parallel view 2





Outside Transect End view