

Jolley – 66S91W 17NESW

Inspection DOC# 675200161

Erosion and sloughing
on cut slope.



Erosion and sloughing
on cut slope.



Staining around tank in
containment.



Valve parts and hand
wheels stored at pig
launcher.

