

## Youberg RWF 33-23

Inspection DOC# 675200186

Erosion on reclamation  
area.



Some erosion and  
rilling on cut slope.

