

## Shideler 19-16C

Inspection DOC# 675200221

Fence in disrepair and  
trash next to  
conductors.



Trash on location





Erosion and rilling on cut slope. Trash in berm.



Trash next to wellheads.

