

PETRO MEX, LLC
P.O. Box 6724
Farmington, NM 87499-6724
Phone: (505) 632-5948 Fax: (505) 634-1503

November 20, 2013

Mr. Carlos Lujan

E-mail: Carlos.Lujan@state.co.us

Dear Mr. Lujan,

I am writing in regard to our conversations about non-compliance issues with our well, the Esmerelda 1-2-8-101. I would like to request from you the following:

1. Please send me the details as to what is required for sampling the two (2) pits on the Esmerelda 1-2-8-101. This would include, but is not limited to, depth, how many places per pit, how many samples and what tests are required.
2. Please send a complete list of all Non-Compliances so we can address them.

As soon as I received the requirements for testing, I will set up a time line to have all the sampling and testing completed. All other Non-Compliance issues will be addressed at this time as well.

Please send all correspondence to my e-mail address: linn_wilson@sisna.com

Truly yours,



Linn Wilson