

Reference Area Photographs

Site Assessment and Remediation Work Plan

Sampling event

July 17, 2014

Maralex

Roan Creek Evaporation Pit

Facility ID # 116525

Maralex Roan Creek Evaporation Pit



Sign at the entrance.



Dry pit. Sediments and salt cover most of the bottom of the pit. Bushes have been removed from around the pit but there is still some vegetation growing right on the border of the pit.

Maralex Roan Creek Evaporation Pit



Drilling to take a sample near the sump



Sampling outside of the fence on the Southeast area. Sampling was done where sediment from the pit perimeter was observed.

Maralex Roan Creek Evaporation Pit



Drilling on the East side of the pit. Sampling was done at selected patch locations, near the bottom of the pit. Samples from 5 locations were collected along the East side of the pit.



Last sample was collected from a point between the tank and the pit (Northwest corner of the pit).