

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

07/21/2014

Document Number:

668800132

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | |
|---------------------|-------------|--------|-----------------|---|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection <input type="checkbox"/> |
| | 231341 | 315683 | GOODWIN, AMANDA | 2A Doc Num: _____ |

Operator Information:OGCC Operator Number: 10081Name of Operator: WINDSOR ENERGY GROUP LLCAddress: 14301 CALIBER DR - SUITE 300City: OKLAHOMA CITY State: OK Zip: 73134

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|-------------------|
| Welter, Earl | 307-686-0891 | ewelter@windsorenergy.com | Operatons Foreman |
| Goodwin, Amanda | | amanda.goodwin@state.co.us | All Inspections |
| CATES, TYKER | (405) 242-6131 | TCATES@WINDSORENERGY.CO | All Inspections |

Compliance Summary:QtrQtr: NWSW Sec: 32 Twp: 2N Range: 102W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 08/24/1999 | 500157575 | ID | SI | | | Pass | No |
| 03/27/1998 | 500157574 | PR | PR | | | | |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|-------------------------------------|
| 231341 | WELL | PA | 08/25/2010 | OW | 103-09011 | UNIVERSITY OF TEXAS 15 | PA | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Inspector Name: GOODWIN, AMANDA

Comment:

Corrective Action:

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Venting:

| Yes/No | Comment |
|--------|---------|
|--------|---------|

Flaring:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
|------|------------------------------|---------|-------------------|---------|

Predrill

Location ID: 231341

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 231341 Type: WELL API Number: 103-09011 Status: PA Insp. Status: PA

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

| | | |
|---|-------------------|-------------|
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ |
| Field Parameters: | | |
| | | |
| Sample Location: _____ | | |
| | | |
| Emission Control Burner (ECB): _____ | | |
| Comment: _____ | | |
| Pilot: _____ Wildlife Protection Devices (fired vessels): _____ | | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: Reference area also severely degraded due to heavy construction traffic in area, (see attached photograph).
Noted mat saltbrush, sagebrush, buffalo grass, rabbitbrush, cheat grass.

Well plugged PassPit mouse/rat holes, cellars backfilled PassDebris removed Pass

No disturbance /Location never built _____

Access Roads Regraded PassContoured Pass

Culverts removed _____

Gravel removed PassLocation and associated production facilities reclaimed PassLocations, facilities, roads, recontoured PassCompaction alleviation Pass

Dust and erosion control _____

Non cropland: Revegetated 80% Pass

Cropland: perennial forage _____

Weeds present PassSubsidence Pass

Comment: Reference area also severely degraded due to heavy construction traffic in area, (see attached photograph).

Corrective Action: _____

Date _____

Overall Final Reclamation PassWell Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|----------|------------|
| Inspection for Final Reclamation purposes only. | GoodwinA | 07/21/2014 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 668800154 | 103-09011_INSP_PHOTO_20140721 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3394909 |