

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/31/2014

Document Number:

674700152

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335981	335981	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 1999 BROADWAY STE 3700City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
White, Brent		bkw@bry.com	Production Foreman
Johnson, Derek	970-285-2200	DSJ@Bry.com	
Burns, Bryan		bob@bry.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Compliance Summary:QtrQtr: Lot 4 Sec: 5 Twp: 6S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/05/2013	663902139			SATISFACTORY			No
06/05/2013	663801091			ACTION REQUIRED	F		No

Inspector Comment:4 cellars and conductors set.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
296741	WELL	XX	05/06/2013	LO	045-16112	CHEVRON 5-27D	ND	<input checked="" type="checkbox"/>
296742	WELL	XX	05/06/2013	LO	045-16113	CHEVRON 5-28D	ND	<input checked="" type="checkbox"/>
296743	WELL	XX	05/06/2013	LO	045-16114	CHEVRON 5-16D	ND	<input checked="" type="checkbox"/>
296744	WELL	XX	05/06/2013	LO	045-16115	CHEVRON 5-24D	ND	<input checked="" type="checkbox"/>
296745	WELL	XX	05/06/2013	LO	045-16116	CHEVRON 5-26D	ND	<input checked="" type="checkbox"/>
296746	WELL	XX	05/06/2013	LO	045-16117	CHEVRON 35-1D	ND	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: LONGWORTH, MIKE

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>6</u>	Production Pits: _____
Condensate Tanks: <u>3</u>	Water Tanks: <u>1</u>	Separators: <u>2</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	Sign at entrance		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	SATISFACTORY	Continue weed control.		

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Open cellars		

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335981

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	kubeczko	Flowback and stimulation fluids must be sent to tanks to allow the sand to settle out before the fluids can be placed into any pipeline or pit located on the well pad. The flowback and stimulation fluid tanks must be placed on the well pad in an area with additional downgradient perimeter berming. The area where flowback fluids will be stored/reused must be constructed to be sufficiently impervious to contain any spilled or released material (per Rule 604.a.(4)). Under unforeseen upset conditions during flowback operations, operator may discharge flowback fluids directly into the pit, as needed (notice of intent to directly discharge into the pit must be sent to Dave Kubeczko; email dave.kubeczko@state.co.us).	12/29/2010
OGLA	kubeczko	Berms or other containment devices shall be constructed in compliance with Rule 603.e.(12) around crude oil, condensate, and produced water storage tanks.	12/29/2010
OGLA	kubeczko	Operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations; including, but not limited to, construction of a berm or diversion dike, diversion/collection trenches within and/or outside of berms/dikes, site grading, or other comparable measures (i.e., best management practices (BMPs) associated with stormwater management) sufficiently protective of nearby surface water. Any berm constructed at the well pad location will be stabilized, inspected at regular intervals (at least every 14 days), and maintained in good condition.	12/29/2010
OGLA	kubeczko	Any pit constructed to hold fluids (reserve pit, production pit, frac pit; except for flare pit, if built) must be lined.	12/29/2010
OGLA	kubeczko	Notify COGCC Oil and Gas Location Assessment (OGLA) Specialist for Western Colorado (Dave Kubeczko; email dave.kubeczko@state.co.us) 48 hours prior to start of construction.	12/29/2010
OGLA	kubeczko	Operator must implement best management practices to contain any unintentional release of fluids, including any fluids conveyed via temporary surface pipelines.	12/29/2010
OGLA	kubeczko	Since the operator will be running up to 10 percent (by volume) diesel oil in the water based drilling mud as a shale stabilization and friction reduction additive while drilling the production hole interval, any pit constructed to hold fluids must be permitted, and approved, prior to construction and use (a Form 15 [Earthen Pit Report/Permit] will need to be submitted). Additional COAs may be attached to the Form 15.	12/29/2010
OGLA	kubeczko	The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.	12/29/2010
OGLA	kubeczko	No portion of any pit that will be used to hold liquids shall be constructed on fill material, unless the pit and fill slope are designed and certified by a professional engineer, subject to review and approval by the director prior to construction of the pit. The construction and lining of the pit shall be supervised by a professional engineer or their agent. The entire base of the pit must be in cut.	12/29/2010

OGLA	kubeczkod	Notice to Operators (NTO) Drilling Wells on the Roan Plateau in Garfield County: Operator must comply with all provisions of the June 12, 2008 Notice to Operators (NTO) Drilling Wells Within ¾ Mile of the Rim of the Roan Plateau in Garfield County – Pit Design, Construction, and Monitoring Requirements. At a minimum, the following condition of approval (COA) will apply: COA 6 - All pits must be lined.	12/29/2010
OGLA	kubeczkod	The nearby hillside must be monitored for any day-lighting of drilling fluids throughout the drilling of the surface casing interval.	12/29/2010

S/A/V: SATISFACTORY**Comment:**

Undrilled location with 4 conductors set.

CA:**Date:****Wildlife BMPs:**

BMP Type	Comment
Drilling/Completion Operations	<p>The following list of Best Management Practices (BMP's) that will be implemented by Berry Petroleum Company during the pad construction, well drilling, well completion, natural gas production and reclamation phases of activity on the Chevron D05 696 well Pad.</p> <p>A total of 6 wells will be directionally drilled from the D05 well pad. Directional drilling has enabled Berry Petroleum Company to reduce the number of well pads required for gas recovery and will minimize surface damage.</p> <p>The D05 well pad will be constructed adjacent to an existing road. This eliminates the need to construct an additional road for access and avoids additional surface disturbance.</p> <p>In general, Berry Petroleum Company will comply with all applicable federal, state and local statutes, rules, regulations and ordinances, including those of OSHA, the COGCC and the CDPHE. Relating to safety and the environment.</p> <p>During construction of the well pad, topsoil will be isolated from other soils and placed and stacked per COGCC requirements. All cuts, fill slopes, pits and topsoil piles will be stabilized and revegetated immediately following construction.</p> <p>The pad will be constructed in compliance with CDPHE Stormwater Discharge regulations. Bear proof dumpsters/trash cans will be used on the location for solid/food waste disposal. Noxious weeds will be controlled.</p> <p>Temporary housing for the drill rig crews will meet all Garfield County regulations. The housing quarters will receive 24/7 supervision by Berry Petroleum Company.</p> <p>Production tanks shall be placed on a non-permeable liner and surrounded by a metal containment wall at least 3 feet in height.</p>

S/A/V: SATISFACTORY**Comment:**

Undrilled location with 4 conductors set.

CA:**Date:****Stormwater:****Comment:****Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 296741 Type: WELL API Number: 045-16112 Status: XX Insp. Status: ND

Facility ID: 296742 Type: WELL API Number: 045-16113 Status: XX Insp. Status: ND

Facility ID: 296743 Type: WELL API Number: 045-16114 Status: XX Insp. Status: ND

Facility ID: 296744 Type: WELL API Number: 045-16115 Status: XX Insp. Status: ND

Facility ID: 296745 Type: WELL API Number: 045-16116 Status: XX Insp. Status: ND

Facility ID: 296746 Type: WELL API Number: 045-16117 Status: XX Insp. Status: ND

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment:

1003a. Debris removed? CM

CA CA Date

Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
4 cellars and conductors set.	longworm	07/31/2014

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674700153	Location sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3399496
674700154	Weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3399497
674700155	Cellars and conductors	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3399498