

Inspector Name: Gomez, Jason

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

07/31/2014

Document Number:

673801239

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 415741 | 415656 | Gomez, Jason | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|---------|
| Fogel, Heather | | HFogel@nobleenergyinc.com | |

Compliance Summary:QtrQtr: SWNW Sec: 13 Twp: 7N Range: 65W**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|-------------------------------------|
| 415741 | WELL | PR | 04/15/2013 | OW | 123-31159 | GREEN USX EE 13-05 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|-----------------------------|-------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: <u>1</u> | Wells: <u>1</u> | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: <u>1</u> | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| BATTERY | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

| | | | | | |
|---|------------------------------|------------------------------|---------------------|-----------------------|---------|
| Spills: | | | | | |
| Type | Area | Volume | Corrective action | CA Date | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Fencing/: | | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date | |
| TANK BATTERY | SATISFACTORY | Wire | | | |
| WELLHEAD | SATISFACTORY | Wire | | | |
| SEPARATOR | SATISFACTORY | Wire | | | |
| Equipment: | | | | | |
| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Horizontal Heated Separator | 1 | SATISFACTORY | | | |
| Ancillary equipment | 1 | SATISFACTORY | Telemetry equipment | | |
| Plunger Lift | 1 | SATISFACTORY | | | |
| Gas Meter Run | 1 | SATISFACTORY | | | |
| Bird Protectors | 1 | SATISFACTORY | | | |
| Emission Control Device | 1 | SATISFACTORY | | | |
| Facilities: <input type="checkbox"/> New Tank Tank ID: _____ | | | | | |
| Contents | # | Capacity | Type | SE GPS | |
| PRODUCED WATER | 1 | <100 BBLS | CONCRETE SUMP/VAULT | 40.575150,-104.619930 | |
| S/A/V: | SATISFACTORY | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

Inspector Name: Gomez, Jason

| | | | | | |
|------------------------|------------------------------|-----------------------------------|---------------------|-----------------------|---------|
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | 40.575150,-104.619930 | |
| S/A/V: | SATISFACTORY | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Venting: | | | | | |
| Yes/No | | Comment | | | |
| NO | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Action Required | | Comment | Corrective Action | CA Date |
| | | | | | |

Predrill

Location ID: 415741

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 415741 Type: WELL API Number: 123-31159 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: Gomez, Jason

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): Y _____

Comment: _____

Pilot: ON _____ Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: CRP

Comment: _____

1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? Pass CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass _____ Production areas stabilized ? Pass _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass _____

Production areas have been stabilized? Pass _____ Segregated soils have been replaced? Pass _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass _____ Recontoured Pass _____ 80% Revegetation Pass _____

1003 f. Weeds Noxious weeds? _____ P _____

Inspector Name: Gomez, Jason

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: CRP

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: vegetation re-growth

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT