

Federal 30-11

Inspection DOC# 675200382

Unused pit is overgrown
with vegetation.



Containment around
tank is full of sediment.



Produced water tank at near capacity.



Location covered in sediment and debris.

