

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
08/12/2014

Document Number:
673705376

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>237432</u>	<u>317251</u>	<u>Sherman, Susan</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>95520</u>
Name of Operator:	<u>WESCO OPERATING INC</u>
Address:	<u>120 S DURBIN STREET</u>
City:	<u>CASPER</u> State: <u>WY</u> Zip: <u>82602</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kirkwood, Robert W.	(307) 577-5300	bk@kirkwoodcompanies.com	
Weinert, Dave	(307) 577-5329	davew@kirkwoodcompanies.com	
Kirkwood, Tom	(307) 472-4618	tomk@kirkwoodcompanies.com	

Compliance Summary:

QtrQtr:	<u>NESE</u>	Sec:	<u>27</u>	Twp:	<u>3S</u>	Range:	<u>51W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/07/2014	673704664	IJ	SI	ACTION REQUIRED			No
07/29/2013	668601175	IJ	AC	SATISFACTOR Y			No
07/13/2012	663400607	IJ	AC	ACTION REQUIRED	P		No
04/19/2011	200308088	RT	AC	SATISFACTOR Y			No
07/14/2010	200262608	MI	AC	SATISFACTOR Y			No
07/06/2009	200214080	RT	AC	SATISFACTOR Y			No
04/16/2008	200130360	RT	AC	SATISFACTOR Y			No
05/10/2007	200111945	RT	AC	SATISFACTOR Y		Pass	No
04/10/2006	200089361	RT	AC	SATISFACTOR Y		Pass	No
06/20/2005	200073033	MI	SI	SATISFACTOR Y		Pass	No
06/16/2005	200073029	MI	SI	ACTION REQUIRED		Fail	Yes
02/10/2005	200066887	MI	SI	SATISFACTOR Y		Pass	No

Inspector Name: Sherman, Susan

11/15/2004	200062834	MI	SI	SATISFACTOR Y		Pass	No
10/25/2004	200062285	MI	SI	SATISFACTOR Y		Pass	No
08/10/2004	200058215	RT	TA	SATISFACTOR Y		Pass	No
07/16/2003	200041679	RT	AC	SATISFACTOR Y		Pass	No
05/15/2002	200027052	MI	AC	SATISFACTOR Y		Pass	No
08/09/2001	200018548	RT	AC	SATISFACTOR Y		Pass	No
06/22/2000	200008050	RT	AC	SATISFACTOR Y		Pass	No
04/09/1996	500159796	DG	AC			Fail	Yes

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107544	PIT		09/23/1999		-	RUDNIK 43B-27	<input type="checkbox"/>
150066	UIC DISPOSAL	CL	06/20/2005		-	RUDNIK 43B-27	CL <input type="checkbox"/>
159125	UIC DISPOSAL	AC	03/24/2005		-	RUDNIK 43B-27	AC <input checked="" type="checkbox"/>
237432	WELL	IJ	11/01/2006	DSPW	121-09933	RUDNIK 43B-27	IJ <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____
 Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____
 Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____
 Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 237432

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 159125 Type: UIC API Number: - Status: AC Insp. Status: AC

Facility ID: 237432 Type: WELL API Number: 121-09933 Status: IJ Insp. Status: IJ

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: LKTA

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 07/14/2010

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: 0 Csg psi: 0 BH psi: _____

Insp. Status: Pass

Comment: **Initial-350 psi, 5 min-349 psi, 10 min-349 psi, 15 min-348 psi, -2 psi lost, PASS.
 Note: 3.5" liner, cemented from 3700', Perforated Interval @ 4340-4404', tubing @ 3673', packer @ 3673'.
 Form 21 and chart attached.**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Inspector Name: Sherman, Susan

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673705377	WESCO Rudnick 43B-27 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3406317
673705378	WESCO Rudnick 43B-27 well MIT Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3406318
673705379	WESCO Rudnick 43B-27 well MIT Chart	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3406319