

Site Photos (05-039-06123) 8/12/2014

Looking towards the East from the West side of location.




Subsidence on west side of location.



Site Photos (05-039-06123) 8/12/2014

Onsite Transect Northeast



Onsite Transect Ground Cover



Site Photos (05-039-06123) 8/12/2014

Onsite Transect Northwest



Onsite Transect Southeast




Site Photos (05-039-06123) 8/12/2014

Onsite Transect Southwest



Offsite Transect South



Site Photos (05-039-06123) 8/12/2014

Offsite Transect Groundcover



Offsite transect East



Site Photos (05-039-06123) 8/12/2014

Offsite transect West

