
Triple Combo
Sonic
Image
Dipole Shear Sonic Imager
Platform Express
Three-Detector Lithology Density
Compensated Thermal Neutron Porofility
Array Induction Imager Tool
Array Induction
Gamma Ray
Caliper
Bit Size
Mud Type
Density Viscosity
Mud Resistivity
Mud Filtrate Resistivity
Mud Cake Resistivity
Mud Density
Mud Viscosity
Source of Sample
Rm @ Measured Temp
Rmf @ Measured Temp
Rmc @ Measured Temp
Source of Rmf and Rmc
Rm @ BHT
Time Since Circulation
Max Recorded Temp
Equipment Number
Location
Recorded By
Witnessed By
Run Number
Depth Driller
Depth Logger
Bottom Logged Interval
Top Log Interval
Casing Driller
Casing Logger
BHT
Logging Disk
Drill Collar Size
Drill Collar Length
Drill Pipe Size
Drill Pipe Length
Max Hole Deviation
Hole Deviation
Max Recorded Temperature



MAUSA (NC-1242)
Well Log Plot
Generated: 2025-08-19 08:00
Prepared by: Petrophysics Team
Validation Report
Validation Date: 2025-08-19 08:00
Validated By: Petrophysics Team
Approved By: Chief Petrophysicist
Quality Control Report
Data Quality Assessment
Overall Quality: Good
Data Completeness: 98.5%
Environmental Corrections Applied
Borehole Corrections: Yes
Temperature Corrections: Yes
Pressure Corrections: Yes
Salinity Corrections: Yes
Depth Corrections Applied
Depth Reference: Kelly Bushing
Depth Shift: 0.0 m
Depth Method: Wireline
Depth Uncertainty: ±0.1 m
Depth Validation Report
Depth Validation Date: 2025-08-19
Depth Validated By: Petrophysics Team
Depth Quality Control
Depth Accuracy: ±0.1 m
Depth Precision: ±0.05 m
Depth Resolution: 0.1 m
Depth Uncertainty Analysis
Depth Uncertainty: ±0.1 m
Depth Confidence Level: 95%
Depth Validation Status: Validated
Depth Quality Control Report
Depth Quality Control Date: 2025-08-19
Depth Quality Control By: Petrophysics Team
Depth Quality Control Status: Approved
Depth Quality Control Comments: Depth validated and approved for use