

# Bar-X 28-3

Inspection DOC# 675200423

Weeds and vegetation in tank containment.



Pump Jack not in use at time of inspection.



Compressor not in use  
at time of inspection.



Blowdown pit

