

Inspector Name: CONKLIN, CURTIS

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

08/20/2014

Document Number:

675200425

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 312366 | 312366 | CONKLIN, CURTIS | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 22370 Name of Operator: D & G ROUSTABOUT SERVICEAddress: 765 S 1/2 ROADCity: MACKState: COZip: 81525**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------------|
| Terrell, David | 970-858-1581 | terrelloil@aol.com | |
| Kellerby, Shaun | | shuan.kellerby@state.co.us | NW Supervisor |

Compliance Summary:QtrQtr: NWSE Sec: 33 Twp: 8S Range: 104W**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------------------------------|
| 116394 | PIT | | 09/23/1999 | | - | C-02508 D | <input type="checkbox"/> |
| 221337 | WELL | PR | 07/18/1995 | | 077-05127 | EAST BAR-X GOVT 1 | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Lease Road:**

| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|------|-----------------------------|---------|-------------------|------|
| Main | Satisfactory | | | |

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|-------------------|-------------------|---------|
| WELLHEAD | Satisfactory | Sign at meter run | | |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

| | | | | | |
|--|------------------------------------|-----------------------------|---------------------|-------------------|------------|
| Spills: | | | | | |
| Type | Area | Volume | Corrective action | CA Date | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Equipment: | | | | | |
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Dehydrator | 1 | Satisfactory | | | |
| Horizontal Separator | 1 | Satisfactory | | | |
| Gas Meter Run | 1 | Satisfactory | | | |
| Facilities: | | | | | |
| <input type="checkbox"/> New Tank | | Tank ID: _____ | | | |
| Contents | # | Capacity | Type | SE GPS | |
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | | |
| S/U/V: | Satisfactory | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | Adequate | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Insufficient | Base Sufficient | Inadequate | |
| Corrective Action | Repair | | | Corrective Date | 09/19/2014 |
| Comment | Holes in berm. See attached photo. | | | | |
| Venting: | | | | | |
| Yes/No | Comment | | | | |
| NO | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date | |
| | | | | | |

Predrill

Location ID: 312366

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:****Comment:****Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 221337 Type: WELL API Number: 077-05127 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat

Long

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Multi-Well Location ☐**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

COGCC Comments

| Comment | User | Date |
|-------------------------|----------|------------|
| Repair berm around tank | conklinc | 08/21/2014 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 675200425 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3414806 |
| 675200426 | Holes in berm | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3414804 |