

Photograph Page 1 of 3

| | |
|---------------------|-------------------------|
| Well/Facility Name: | Lee 7, 17, 21, 25, 28-6 |
|---------------------|-------------------------|



Photograph 1. This is the North facing photograph, as defined in regulation 1003.e.(3).

Date Taken: 6/11/2014

GPS Location: 40.17306/-104.70404



Photograph 2. This is the South facing photograph, as defined in regulation 1003.e.(3).

Date Taken: 6/11/2014

GPS Location: 40.17306/-104.70404

Photograph Page 2 of 3

| | |
|---------------------|-------------------------|
| Well/Facility Name: | Lee 7, 17, 21, 25, 28-6 |
|---------------------|-------------------------|



Photograph 3. This is the East facing photograph, as defined in regulation 1003.e.(3).
Date Taken: 6/11/2014
GPS Location: 40.17306/-104.70404



Photograph 4. This is the West facing photograph, as defined in regulation 1003.e.(3).
Date Taken: 6/11/2014
GPS Location: 40.17306/-104.70404

Photograph Page 3 of 3

| | |
|---------------------|-------------------------|
| Well/Facility Name: | Lee 7, 17, 21, 25, 28-6 |
|---------------------|-------------------------|



Photograph 5. This is the reference photograph of the site, as defined in regulation 1003.e.(3).

Date Taken: 6/11/2014

GPS Location: 40.17306/-104.70404



Photograph 6. This is the reference photograph of the representative total coverage of the adjacent or nearby undisturbed land, as defined in regulation 1003.e.(3).

Date Taken: 6/11/2014

GPS Location: 40.17306/-104.70404