

Location Photos

Northerly

Date Photographed: 06-02-14

Photographed By : C.S.

NAD 83 - Decimal Degrees

Latitude : 40.766792

Longitude : 103.781449



Easterly

Date Photographed: 06-02-14

Photographed By : C.S.

NAD 83 - Decimal Degrees

Latitude : 40.767112

Longitude : 103.782160



**Tri State
Land Surveying, Inc.**

180 NORTH VERNAL AVE. VERNAL, UTAH 84078

P: (435) 781-2501
F: (435) 781-2518

DRAWN BY: A.P.C. REVISED:

DATE: 07-10-14

WHITING OIL & GAS CORP.

Cottonwood 08E
Sec. 8, T9N, R57W, 6th P.M.
Weld County, CO.

COLOR PHOTOGRAPHS

SHEET

P2

Location Photos

Southerly


Date Photographed: 06-02-14

Photographed By : C.S.

NAD 83 - Decimal Degrees

Latitude : 40.767421

Longitude : 103.781326



Westerly

Date Photographed: 06-02-14

Photographed By : C.S.

NAD 83 - Decimal Degrees

Latitude : 40.767099

Longitude : 103.780605



Tri State
Land Surveying, Inc.
180 NORTH VERNAL AVE. VERNAL, UTAH 84078

P: (435) 781-2501
F: (435) 781-2518

DRAWN BY: A.P.C. REVISED:
DATE: 07-10-14

WHITING OIL & GAS CORP.

Cottonwood 08E
Sec. 8, T9N, R57W, 6th P.M.
Weld County, CO.

COLOR PHOTOGRAPHS

SHEET
P3