

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

09/23/2014

Document Number:

675100463

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 231967      | 316038 | GRANAHAH, KYLE  | <input type="checkbox"/> |             |

**Operator Information:**OGCC Operator Number: 49100Name of Operator: KOCH EXPLORATION COMPANY, LLCAddress: 950 17TH STREET #1900City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Clark, John     | 505-334-9111 | clark23j@kochind.com       |         |
| Kellerby, Shaun |              | shaun.kellerby@state.co.us |         |

**Compliance Summary:**QtrQtr: NESE Sec: 29 Twp: 2N Range: 97W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 07/12/2012 | 662300669 | PR         | PR          | <b>ACTION REQUIRED</b>        | P        |                | No              |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|-------------------------------------|
| 231967      | WELL | PR     | 11/10/1993  | GW         | 103-09638 | FEDERAL 29-9     | SI          | <input checked="" type="checkbox"/> |
| 434292      | PIT  | CL     | 10/24/2013  |            | -         | WRD Federal 29-9 | CL          | <input type="checkbox"/>            |

**Equipment:**Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

| <b>Signs/Marker:</b> |                              |   |                   |         |
|----------------------|------------------------------|---|-------------------|---------|
| Type                 | Satisfactory/Action Required | Comment   | Corrective Action | CA Date |
| WELLHEAD             | SATISFACTORY                 | Provide nearest public access road on sign, reattach fallen sign to wellhead. |                   |         |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Spills:</b> |      |        |                   |         |
|----------------|------|--------|-------------------|---------|
| Type           | Area | Volume | Corrective action | CA Date |

☐ Multiple Spills and Releases?

| <b>Equipment:</b>  |   |                              |         |                   |         |
|--------------------|---|------------------------------|---------|-------------------|---------|
| Type               | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Deadman # & Marked | 4 | SATISFACTORY                 |         |                   |         |
| Gas Meter Run      | 1 | SATISFACTORY                 |         |                   |         |

| <b>Venting:</b> |         |  |
|-----------------|---------|--|
| Yes/No          | Comment |  |
| NO              |         |  |

| <b>Flaring:</b> |                              |         |                   |         |
|-----------------|------------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                 |                              |         |                   |         |

**Predrill**

Location ID: 231967

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 231967 Type: WELL API Number: 103-09638 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

S/A/V: SATISFACTORY CA Date: \_\_\_\_\_

CA: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: GRANAHAN, KYLE

|   |  |                              |            |
|---|--|------------------------------|------------|
| Comment: <input style="width:700px" type="text"/>         |  |                              |            |
| Corrective Action: _____                                  |  | Date: _____                  |            |
| Reportable: _____   | GPS: Lat _____                                     | Long _____                   |            |
| Proximity to Surface Water: _____                         |  | Depth to Ground Water: _____ |            |
| <b>Water Well:</b>  |  |                              |            |
|   |  | Lat _____                    | Long _____ |
| DWR Receipt Num: _____                                    | Owner Name: _____                                  | GPS : _____                  |            |
| <b>Field Parameters:</b>                                  |  |                              |            |
| <input style="width:300px" type="text"/>                  |  |                              |            |
| Sample Location: <input style="width:400px" type="text"/> |  |                              |            |
| Emission Control Burner (ECB): _____                      |  |                              |            |
| Comment: _____  |  |                              |            |
| Pilot: _____  | Wildlife Protection Devices (fired vessels): _____ |                              |            |

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

|   |   |
|---|---|
| Date Interim Reclamation Started: _____           | Date Interim Reclamation Completed: _____   |
| Land Use: _____                                   |   |
| Comment: <input style="width:750px" type="text"/> |   |
| 1003a.  | Debris removed? _____ CM _____  |
|   | CA _____ CA Date _____  |
|   | Waste Material Onsite? _____ CM _____   |
|   | CA _____ CA Date _____  |
|   | Unused or unneeded equipment onsite? _____ CM _____   |
|   | CA _____ CA Date _____  |
|   | Pit, cellars, rat holes and other bores closed? _____ CM _____  |
|   | CA _____ CA Date _____  |
|   | Guy line anchors removed? _____ CM _____  |
|   | CA _____ CA Date _____  |
|   | Guy line anchors marked? _____ CM _____   |
|   | CA _____ CA Date _____  |
| 1003b.  | Area no longer in use? _____ Production areas stabilized ? _____  |
| 1003c.  | Compacted areas have been cross ripped? _____   |
| 1003d.  | Drilling pit closed? _____ Subsidence over on drill pit? _____  |
|   | Cuttings management: _____  |
| 1003e.  | Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ |
|   | Production areas have been stabilized? _____ Segregated soils have been replaced? _____                               |
| <b>RESTORATION AND REVEGETATION</b>               |   |
| <u>Cropland</u>                                   |   |
| Top soil replaced _____                           | Recontoured _____ Perennial forage re-established _____   |

Inspector Name: GRANAHAN, KYLE

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
|         | 434292      | 400314905  |                 |