

## **Reference Area Photographs**

**Inspection Conducted on September 11 and 16, 2014**

**URSA**

**Lungren Frac/Flowback Pit**

**Location ID #324342**

**Pit Facility ID #282224**

**Garfield County**

## URSA Lungren A1 Pad



Sign at the entrance.



Removing the felt and the plastic portion of the liner.



## URSA Lungren A1 Pad



Wrapping up the plastic part of the liner for recycling (cut in 8' by 8' pieces).



View of the pad from the pit looking West.



## URSA Lungren A1 Pad



Shut-in well.



Monitoring well located near the Southwest corner of the pit.



## URSA Lungren A1 Pad



Pit liner removed. Consultant taking samples from the bottom of the pit.



Using PID and Petroflag to screen soil samples for volatile hydrocarbons.



## URSA Lungren A1 Pad



Preparing sample for Petroflag reading



Filtering material for Petroflag reading.