

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:  
10/02/2014Document Number:  
668302748Overall Inspection:  
SATISFACTORY**FIELD INSPECTION FORM**

|                     |             |        |                  |   |
|---------------------|-------------|--------|------------------|---|
| Location Identifier | Facility ID | Loc ID | Inspector Name:  | On-Site Inspection <input type="checkbox"/> |
|                     | 275798      | 333133 | JOHNSON, RANDELL | 2A Doc Num: _____                           |

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name | Phone        | Email                          | Comment                    |
|--------------|--------------|--------------------------------|----------------------------|
| Group, Email |              | cogcc.djinspections@encana.com | Group Email                |
| House, Chris | 303-774-3972 | larry.house@encana.com         | Strategic Projects Advisor |

**Compliance Summary:**QtrQtr: NWSW Sec: 33 Twp: 2N Range: 68W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 01/18/2011 | 200293968 | PR         | PR          | ACTION REQUIRED               |          |                | Yes             |
| 06/15/2005 | 200073079 | DG         | WO          | SATISFACTORY                  | F        | Fail           | No              |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|-------------------------------------|
| 241406      | WELL | PR     | 08/13/2014  | GW         | 123-09195 | OSKARSON 3     | PR          | <input type="checkbox"/>            |
| 275798      | WELL | PR     | 06/18/2005  | GW         | 123-22678 | OSKARSON 13-33 | SI          | <input checked="" type="checkbox"/> |

**Equipment:****Location Inventory**

|                             |                        |                     |                         |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____     | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____  | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____      | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____      | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

| <b>Signs/Marker:</b> |                              |         |                   |         |
|----------------------|------------------------------|---------|-------------------|---------|
| Type                 | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD             | SATISFACTORY                 |         |                   |         |
| BATTERY              | SATISFACTORY                 |         |                   |         |
| TANK LABELS/PLACARDS | SATISFACTORY                 |         |                   |         |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Fencing/:</b> |                              |                      |                   |         |
|------------------|------------------------------|----------------------|-------------------|---------|
| Type             | Satisfactory/Action Required | Comment              | Corrective Action | CA Date |
| SEPARATOR        | SATISFACTORY                 | Chain-link fencing   |                   |         |
| WELLHEAD         | SATISFACTORY                 | Pipe and rod fencing |                   |         |
| TANK BATTERY     | SATISFACTORY                 | Chain-link fencing   |                   |         |

| <b>Equipment:</b>           |   |                              |  |                   |         |
|-----------------------------|---|------------------------------|--|-------------------|---------|
| Type                        | # | Satisfactory/Action Required | Comment  | Corrective Action | CA Date |
| Emission Control Device     | 2 | SATISFACTORY                 |  |                   |         |
| Gas Meter Run               | 1 | SATISFACTORY                 | Pipeline meter and metal meter run house       |                   |         |
| Vertical Separator          | 1 | SATISFACTORY                 |  |                   |         |
| Horizontal Heated Separator | 3 | SATISFACTORY                 |  |                   |         |
| Gas Meter Run               | 3 | SATISFACTORY                 | Operator check meters on outlets of separators |                   |         |
| Plunger Lift                | 1 | SATISFACTORY                 |  |                   |         |

|                    |              |                                   |                   |                       |
|--------------------|--------------|-----------------------------------|-------------------|-----------------------|
| <b>Facilities:</b> |              | <input type="checkbox"/> New Tank | Tank ID: _____    |                       |
| Contents           | #            | Capacity                          | Type              | SE GPS                |
| PRODUCED WATER     | 1            | OTHER                             | PBV FIBERGLASS    | 40.089650,-105.013930 |
| S/A/V:             | SATISFACTORY |                                   | Comment: 235 bbls |                       |
| Corrective Action: |              |                                   |                   | Corrective Date:      |

Paint

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

|       |          |                     |                     |             |
|-------|----------|---------------------|---------------------|-------------|
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                   |                 |
|-------------------|-----------------|
| Corrective Action | Corrective Date |
| Comment           |                 |

|                    |              |                                   |                   |                       |
|--------------------|--------------|-----------------------------------|-------------------|-----------------------|
| <b>Facilities:</b> |              | <input type="checkbox"/> New Tank | Tank ID: _____    |                       |
| Contents           | #            | Capacity                          | Type              | SE GPS                |
| CONDENSATE         | 3            | OTHER                             | STEEL AST         | 40.089650,-105.013930 |
| S/A/V:             | SATISFACTORY |                                   | Comment: 330 bbls |                       |
| Corrective Action: |              |                                   |                   | Corrective Date:      |

Paint

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

|       |          |                     |                     |             |
|-------|----------|---------------------|---------------------|-------------|
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                   |                 |
|-------------------|-----------------|
| Corrective Action | Corrective Date |
| Comment           |                 |

|                 |         |  |
|-----------------|---------|--|
| <b>Venting:</b> |         |  |
| Yes/No          | Comment |  |
| NO              |         |  |

|                 |                              |         |                   |         |
|-----------------|------------------------------|---------|-------------------|---------|
| <b>Flaring:</b> |                              |         |                   |         |
| Type            | Satisfactory/Action Required |         |                   |         |
|                 |                              | Comment | Corrective Action | CA Date |
|                 |                              |         |                   |         |

**Predrill**

Location ID: 275798

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 275798 Type: WELL API Number: 123-22678 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

S/A/V: \_\_\_\_\_ CA Date: \_\_\_\_\_

CA: \_\_\_\_\_

Comment: Producing intermittently

**BradenHead**

Comment: Bradenhead is plumbed to the surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): Y \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: ON \_\_\_\_\_ Wildlife Protection Devices (fired vessels): YES \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? In \_\_\_\_\_ Production areas stabilized ? Pass \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

Inspector Name: JOHNSON, RANDELL

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
Cuttings management: \_\_\_\_\_  
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In  
Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment    |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |            |
| Other            | Pass            | Other                   | Pass                  |               |                          | Vegetation |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |            |

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT