

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
10/02/2014

Document Number:
675200618

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>334367</u>	<u>334367</u>	<u>CONKLIN, CURTIS</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bonkiewicz, Mike	(970) 625-1494	mbonkiewicz@nobleenergyinc.com	District Manager
Pavelka, Linda	(303) 228-4060	lpavelka@nobleenergyinc.com	Regulatory Analyst
Kellerby, Shaun		shuan.kellerby@state.co.us	NW Supervisor

Compliance Summary:

QtrQtr: SENV Sec: 1 Twp: 8S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/06/2013	663800967			SATISFACTORY			No
05/06/2013	663800969			SATISFACTORY	I		No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275512	WELL	AL	11/14/2006	LO	045-10332	M.DUTTON 1-33	AL <input type="checkbox"/>
288328	WELL	PR	01/07/2011	GW	045-13200	M. DUTTON 1-22A	PR <input checked="" type="checkbox"/>
288329	WELL	PR	08/26/2009	GW	045-13199	M. DUTTON 1-22B	PR <input checked="" type="checkbox"/>
288330	WELL	PR	08/26/2009	GW	045-13198	M.DUTTON 1-22C	PR <input checked="" type="checkbox"/>
288331	WELL	PR	12/22/2008	GW	045-13197	M.DUTTON 1-22D	PR <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location					
Lease Road:					
Type	Satisfactory/Action Required	comment	Corrective Action	Date	
Access	SATISFACTORY				
Signs/Marker:					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	
TANK LABELS/PLACARDS	SATISFACTORY				
WELLHEAD	SATISFACTORY				
Emergency Contact Number (S/A/V): <u>SATISFACTORY</u> Corrective Date: _____					
Comment: _____					
Corrective Action: _____					
Good Housekeeping:					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	
DEBRIS	ACTION REQUIRED	Debris on location. See attached photo	Remove	10/30/2014	
Spills:					
Type	Area	Volume	Corrective action	CA Date	
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	
SEPARATOR	SATISFACTORY	Wire panels			
WELLHEAD	SATISFACTORY	Wire panels			
TANK BATTERY	SATISFACTORY	Wire panels			
Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	4	SATISFACTORY	Earth berm containmnet		
Plunger Lift	4	SATISFACTORY			
Bird Protectors	2	SATISFACTORY			
Gathering Line	1	SATISFACTORY			

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST	,	
S/AV:	SATISFACTORY		Comment: Sour condensate		
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action					Corrective Date
Comment					
Venting:					
Yes/No	Comment				
NO					
Flaring:					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

Predrill

Location ID: 334367

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 288328 Type: WELL API Number: 045-13200 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 288329 Type: WELL API Number: 045-13199 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 288330 Type: WELL API Number: 045-13198 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 288331 Type: WELL API Number: 045-13197 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):
Comment:
Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:
Land Use:
Comment:
1003a. Debris removed? CM CA Date
Waste Material Onsite? CM CA Date
Unused or unneeded equipment onsite? CM CA Date
Pit, cellars, rat holes and other bores closed? CM CA Date
Guy line anchors removed? CM CA Date
Guy line anchors marked? CM CA Date
1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Seeding	Pass					

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675200631	Debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3451919