

**Site Photos (05-073-06379) 10/2/2014**

Center of location looking North




Center of location looking West





**Site Photos (05-073-06379) 10/2/2014**

Center of location looking South



Center of location looking East





Site Photos (05-073-06379) 10/2/2014

Weed growth on location: Puncture Vine



Weed growth on location: Russian thistle





**Site Photos (05-073-06379) 10/2/2014**

Gate was down on Northeast side of location



Surrounding Vegetation/ Reference Area

