


Location # 045-22522 Operator: WPX ENERGY ROCKY MOUNTAIN LLC

Inspection Photographs (22 total) 10/16 & 10/20, 2014



1. Location, overlaid on Google Earth, 2014.

10/16/2014



2. Location access road entrance, viewed NW from SE.



3. Location access road entrance, viewed SW from NE.



4. Location access road, viewed SW from NE.



5. Location entrance, viewed West from East.



6. Location Eastern perimeter topsoil stripping, viewed South from South side of entrance.



7. Location Eastern perimeter topsoil stripping,, viewed North from SE corner of survey markers.



8. Location topsoil stripping at SE corner, viewed South.



9. Location topsoil stripping on South perimeter, viewed West from SE corner..



10. Location and brush hogging, viewed North from SE perimeter center.



11. Location topsoil stripping on West perimeter, viewed North from SW corner.



12. Location topsoil stripping on North perimeter, viewed East from NSW corner.



13. Location topsoil stockpile, viewed North from Western perimeter.



14. Location East perimeter, viewed North from South of entrance.

10/20/2014



15. Pad entrance, viewed NE from SW.



16. Pad eastern perimeter, viewed SW from entrance.



17. Pad eastern perimeter, viewed NE from entrance.



18. View from center of pad, looking North.



19. View from center of pad, looking East.



20. View from center of pad, looking South.



21. View from center of pad, looking West.



22. Northern perimeter and soil stockpile, viewed East from NW corner.