

Order Finding Violation Hearing Maralex Resources, Inc. Docket 1410-OV-53

October 27-28, 2014

**Exhibit 3 -
Katie Eileen 2 & 3 Wells**

Unlined Pit

**Spring Creek
Extension Ditch**

**Pit with Torn
Liner**

Google earth

1993

Imagery Date: 5/2/2013 37°08'33.73" N 107°34'28.18" W elev 6712 ft eye alt 7337 ft

Exhibit 16A



04.11.2014 10:08

Exhibit 16A - Pit with Torn Liner



Figure 2: Location of Sample #4, lined drill pit.

Exhibit 16B



04.11.2014 09:50

Exhibit 16B - Unlined Pit



Figure 1: Unlined pit near the Katie Eileen 34-7-35 #2, location of Sample #1.



Figure 2: Sample location #2, where flow pattern exists.