

**Site Photos: API# 05-073-06489**

**Date: November 20, 2014**



**photo 1:** Access Road to the location, facing West.



**photo 2:** Access road is establishing vegetation well on in this segment.



**Site Photos: API# 05-073-06489**

**Date: November 20, 2014**



**photo 3:** Center of the location facing North.



**photo 4:** Center of the location facing West.



**Site Photos: API# 05-073-06489**

**Date: November 20, 2014**



**photo 5:** Center of the location facing South.



**photo 6:** Center of the location facing East.



**Site Photos: API# 05-073-06489**

**Date: November 20, 2014**



**photo 7:** Weed cover (Russian thistle) throughout the location.



**photo 8:** Surrounding vegetation, reference area.