

Site Photos: API# 05-073-06488

Date: November 20, 2014



photo 1: Access Road East, to the location.



photo 2: Facing East towards the location on the access road.

Site Photos: API# 05-073-06488

Date: November 20, 2014



photo 3: Center of the location facing North.



photo 4: Center of the location facing West.

Site Photos: API# 05-073-06488

Date: November 20, 2014



photo 5: Center of the location facing South.



photo 6: Center of the location facing East.

Site Photos: API# 05-073-06488

Date: November 20, 2014



photo 7: Weed cover (Russian thistle, Kochia) throughout the location.



photo 8: Erosion occurring through the center of the location has created a ditch.

Site Photos: API# 05-073-06488

Date: November 20, 2014



photo 9: Fence around the location appeared to be in good condition. Gate had been left open.



photo 10: Surrounding vegetation, reference area.