

Site Photos: API# 05-017-07697

Date: November 19, 2014



photo 1: Access Road to the location, facing South.



photo 2: Facing South at location from the access road.

Site Photos: API# 05-017-07697

Date: November 19, 2014



photo 3: Center of the location facing North.



photo 4: Center of the location facing West.

Site Photos: API# 05-017-07697

Date: November 19, 2014



photo 5: Center of the location facing South.



photo 6: Center of the location facing East.

Site Photos: API# 05-017-07697

Date: November 19, 2014



photo 7: Facing East, bales left on location.



photo 8: Facing North towards the access road from the location.

Site Photos: API# 05-017-07697

Date: November 19, 2014



photo 9: Shovel could not break through soil surface indicating soil compaction.



photo 10: Surrounding vegetation, reference area.