

Site Photos: API# 05-125-10877

Date: November 21, 2014



photo 1: Well sign.



photo 2: Access road to the location.

Site Photos: API# 05-125-10877

Date: November 21, 2014



photo 3: Facing North at location.



photo 4: Ground had recently been ripped on location and in the surrounding pasture.

Site Photos: API# 05-125-10877

Date: November 21, 2014




photo 5: Facing Southwest at the location.



photo 6: Guyline markers were present.