

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
12/10/2014Document Number:
673801610Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	319203	319203	Gomez, Jason	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 20203 HIGHWAY 60City: PLATTEVILLE State: CO Zip: 80651

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED
☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Pennington, Dave		dpennington@syrginfo.com	Synergy Inspection

Compliance Summary:QtrQtr: SWSE Sec: 29 Twp: 1N Range: 68W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
243070	WELL	TA	03/05/2013	OW	123-10861	PRATT 29-3	TA	<input type="checkbox"/>
418031	WELL	AL	12/28/2010	LO	123-31817	SRC Pratt 44-29D	AL	<input type="checkbox"/>
418033	WELL	PR	06/05/2011	OW	123-31819	SRC Pratt 34-29D	PR	<input checked="" type="checkbox"/>
418034	WELL	PR	07/05/2011	OW	123-31820	SRC Pratt 43-29D	PR	<input checked="" type="checkbox"/>
418035	WELL	PR	12/14/2012	GW	123-31821	SRC Pratt 29TD	PR	<input checked="" type="checkbox"/>
418036	WELL	PR	12/14/2012	OW	123-31822	SRC Pratt 29XD	PR	<input checked="" type="checkbox"/>
421226	WELL	PR	07/05/2011	OW	123-32857	SRC Pratt 29PD	PR	<input checked="" type="checkbox"/>
421239	WELL	PR	10/05/2011	OW	123-32862	SRC Pratt 33-29D	PR	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: Gomez, Jason

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>7</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>3</u>	Separators: <u>6</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>6</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>2</u>	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
WELLHEAD	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
WELLHEAD	SATISFACTORY			
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK BATTERY	SATISFACTORY	6' metal fence		
SEPARATOR	SATISFACTORY	6' metal fence		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Bird Protectors	8	SATISFACTORY			
Horizontal Heated Separator	5	SATISFACTORY			
Horizontal Heated Separator	1	ACTION REQUIRED	Burner is not adjusted to reduce sound coming from burner	Adjust burner to reduce sound coming from separator	01/10/2015
Plunger Lift	6	SATISFACTORY			
Gas Meter Run	5	SATISFACTORY			
Emission Control Device	2	SATISFACTORY			

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	2	200 BBLS	PBV FIBERGLASS	40.017390,-105.022830
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:			Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	Corrective Date
-------------------	-----------------

Comment

Facilities:	<input type="checkbox"/> New Tank	Tank ID: _____
--------------------	-----------------------------------	----------------

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	7	300 BBLS	STEEL AST	40.017390,-105.022830

S/A/V:	SATISFACTORY		Comment:	
--------	--------------	--	----------	--

Corrective Action:	Corrective Date:
--------------------	------------------

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	Corrective Date
-------------------	-----------------

Comment

Venting:		
Yes/No	Comment	
NO		

Flaring:				
Type	Satisfactory/Action Required			

Inspector Name: Gomez, Jason

Predrill

Location ID: 319203

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 418033 Type: WELL API Number: 123-31819 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 418034 Type: WELL API Number: 123-31820 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 418035 Type: WELL API Number: 123-31821 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Inspector Name: Gomez, Jason

Facility ID: 418036 Type: WELL API Number: 123-31822 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 421226 Type: WELL API Number: 123-32857 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 421239 Type: WELL API Number: 123-32862 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB): Y

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: DRY LAND

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? CM

Inspector Name: Gomez, Jason

CA _____ CA Date _____
Guy line anchors removed? Pass CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND, RESIDENTIAL

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Inspector Name: Gomez, Jason

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT