


Pallaoro 23-12H

Inspection# 675200946

Sediment run-on to location.



Trash at wellhead.



Unmarked deadman, trash and sediment run-on.



Trash in tank containment.

