

**Document Number: TBD from data entered Form 27****Location ID: 325293****Williford Resources LLC, Long and Schluter #6 Pit Closure, Section 7, T33N, R11W, N PM, La Plata County, Colorado, Form 27 Conditions of Approval (COAs)****Conditions of Approval:**

Conditionally approved, however, additional information or activities may be required during the course of remediation.

**PIT**

According to the Form 27 submitted by the operator, it is proposed that this historical pit (Pit Facility ID #118933) will be backfilled with clean soil and reseeded. Initial sampling results indicate TPH levels above Table 910-1 standards.

Remediation efforts must be performed before this pit may be backfilled and reclaimed. A supplemental remediation work plan shall be submitted to COGCC SW EPS detailing proposed remediation efforts.

This supplemental Form 27 or report shall include the following information:

-A proposed sampling plan to describe how the contents of the pit will be adequately characterized. Enough discrete samples shall be collected to adequately characterize the pit contents. These samples will be analyzed for the constituents in Table 910-1. Composite samples will not be accepted for this site characterization.

-A detailed remediation/reclamation work plan will address the corrective actions proposed by the operator.

-Should any impacted material be removed from the location for disposal at an approved facility, haul tickets or waste manifests shall be provided.

The operator will adhere to the rules and regulations set forth in the 900 and 1000 series rules regarding pit closure and reclamation.

**Williford Resources LLC, Long and Schluter #6 Pit Closure, Section 7, T33N, R11W, N PM, La Plata County, Colorado, Form 27 Conditions of Approval (COAs)**